



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | BORA 8V |
| Colour | Green |
| Year of manufacture | - |
| Top speed | 115 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 115 BHP |
| Max. torque | 169 Nm at 2.400 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 23.9 mpg |
| Consumption extra urban | 40.9 mpg |
| Consumption combined | 32.5 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-11-28 |
| Pictures | 13 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #24 | 2022-12-16 16:55 |
| MOT test number | 756774082570 |
| Result | ✓ Passed |
| Next expiry date | 2023-12-17 |
| Advice | Nearside Play in steering rack inner joint(s) |
| Advice | Offside Play in steering rack inner joint(s) |

| | |
|------------------------|---|
| MOT #23 | 2022-12-15 18:14 |
| MOT test number | 836004478394 |
| Result | ✗ Failed |
| Advice | Nearside Play in steering rack inner joint(s) |
| Fail | Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b)) |
| Advice | Offside Play in steering rack inner joint(s) |
| Fail | Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) |

| | |
|------------------------|---|
| MOT #22 | 2022-12-15 13:16 |
| MOT test number | 255613984955 |
| Result | ✗ Failed |
| Fail | Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) |
| Fail | Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Front Play in steering rack inner joint(s) |
| Fail | Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b)) |
| Fail | Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) |

| | |
|------------------------|------------------|
| MOT #21 | 2021-12-03 11:31 |
| MOT test number | 582358316779 |
| Result | ✓ Passed |

**MOT #20** 2020-12-09 14:09**MOT test number** 693553752432**Result** ✓ Passed**MOT #19** 2020-12-09 14:09**MOT test number** 314192364768**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**MOT #18** 2019-12-16 16:18**MOT test number** 956707998332**Result** ✓ Passed**MOT #17** 2018-12-18 15:19**MOT test number** 637014865655**Result** ✓ Passed**MOT #16** 2017-11-27 11:13**MOT test number** 982304324944**Result** ✓ Passed**Advice** Exhaust emissions just passed**MOT #15** 2017-11-25 10:02**MOT test number** 771545717954**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Advice** Exhaust emissions just passed

**MOT #14** 2016-12-05 15:25**MOT test number** 336283666997**Result** ✓ Passed**MOT #13** 2015-12-15 11:25**MOT test number** 332281997594**Result** ✓ Passed**Advice** Interior mirror deteriorated**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2014-12-15 14:01**MOT test number** 465729244377**Result** ✓ Passed**MOT #11** 2013-11-21 10:04**MOT test number** 517945323377**Result** ✓ Passed**MOT #10** 2012-11-08 15:40**MOT test number** 408853712473**Result** ✓ Passed**MOT #9** 2011-11-11 15:25**MOT test number** 835625511316**Result** ✓ Passed



| | |
|---------------|------------------|
| MOT #8 | 2010-10-29 16:37 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 934782300332 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #7 | 2010-10-29 16:37 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 904882500350 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✗ Failed |
|---------------|----------|

| | |
|--------------------------------|--|
| Pass with rectification | Offside Stop lamp not working (1.2.1b) |
|--------------------------------|--|

| | |
|---------------|------------------|
| MOT #6 | 2009-08-10 09:05 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 444922229224 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2008-07-18 13:29 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 722030008253 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2007-09-25 10:39 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 593808067279 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2006-09-26 11:27 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 572459766278 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



| | |
|-------------------------|--|
| MOT #2 | 2006-09-26 11:27 |
| MOT test number | 710609966275 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Pass with rectification | Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i) |
| Pass with rectification | Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Pass with rectification | Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i) |

| | |
|-----------------|------------------|
| MOT #1 | 2005-09-22 11:05 |
| MOT test number | 304665765248 |
| Result | ✓ Passed |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | W299XKO |
| Plate since | 2019-03-29 |
| Current registration | W299XKO |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2000-03-06 |
| Last registration | 2022-12-16 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2000-03-06 | 19 mi |
| Registration #2 | 2005-09-22 | 35.093 mi |
| Registration #3 | 2006-09-26 | 38.968 mi |
| Registration #4 | 2007-09-25 | 42.898 mi |
| Registration #5 | 2008-07-18 | 45.608 mi |
| Registration #6 | 2009-08-10 | 49.777 mi |
| Registration #7 | 2010-10-29 | 54.933 mi |
| Registration #8 | 2011-11-11 | 58.872 mi |
| Registration #9 | 2012-11-08 | 63.907 mi |
| Registration #10 | 2013-11-21 | 68.906 mi |
| Registration #11 | 2014-12-15 | 74.839 mi |
| Registration #12 | 2015-12-15 | 81.910 mi |
| Registration #13 | 2016-01-01 | 85.000 mi |
| Registration #14 | 2016-01-01 | 85.000 mi |
| Registration #15 | 2016-01-01 | 85.000 mi |
| Registration #16 | 2016-01-01 | 85.000 mi |
| Registration #17 | 2016-01-01 | 85.000 mi |
| Registration #18 | 2016-01-01 | 85.000 mi |
| Registration #19 | 2016-01-01 | 85.000 mi |
| Registration #20 | 2016-01-01 | 85.000 mi |
| Registration #21 | 2016-01-01 | 85.000 mi |
| Registration #22 | 2016-01-01 | 85.000 mi |
| Registration #23 | 2016-01-01 | 85.000 mi |
| Registration #24 | 2016-01-01 | 85.000 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1724 mm |
| Height | 1498 mm |
| Length | 4081 mm |
| Wheel base | 2508 mm |
| Max. allowed weight | 1710 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of axles | 2 |

Engine number

AQY116884