



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO D-4D TR
Colour	Grey
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-08-31
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	7
Total items failed	33

MOT #15	2020-09-01 09:31
MOT test number	732776009313
Result	✓ Passed
Next expiry date	2021-08-31

MOT #14	2020-09-01 09:31
MOT test number	374087671649
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13**

2020-08-17 15:01

MOT test number

528612269687

Result

✗ Failed

- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #12

2019-01-26 13:16

MOT test number

543816743362

Result

✓ Passed

MOT #11

2019-01-26 13:16

MOT test number

105717318036

Result

✗ Failed

- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #10

2017-10-25 14:32

MOT test number

472638380724

Result

✓ Passed



MOT #9	2016-11-11 11:57
MOT test number	904024450538
Result	✓ Passed
Advice Offside Front fog lamp lense broken.	

MOT #8	2016-11-10 10:12
MOT test number	953081262923
Result	✗ Failed
Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure bold patch in tread. (4.1.D.1b)	
Advice Offside Front fog lamp lense broken.	
Fail Offside Front Tyre tread depth below requirements of 1.6mm bold patches on inner edge. (4.1.E.1)	
Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Rear brake pads getting low.	
Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure been run flat and sidewall damaged. (4.1.D.1b)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	

MOT #7	2015-11-13 14:45
MOT test number	522528970288
Result	✓ Passed

**MOT #6** 2015-11-06 11:01**MOT test number** 311794063314**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Fail** Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Direction indicator excessively deteriorated so that it is not visible from a reasonable distance (1.4.A.2e)
- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Direction indicator excessively deteriorated so that it is not visible from a reasonable distance (1.4.A.2e)

MOT #5 2014-11-14 12:37**MOT test number** 588568614353**Result** ✓ Passed**MOT #4** 2014-11-13 12:55**MOT test number** 678467614359**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #3	2013-11-05 09:59
MOT test number	369639503307
Result	✓ Passed
MOT #2	2012-10-26 15:32
MOT test number	288070302327
Result	✓ Passed
MOT #1	2012-10-26 15:32
MOT test number	659280602325
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)
Pass with rectification	Offside Front Headlamp aim too low (1.8)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	KR59FJF
Plate since	2019-03-29
Current registration	KR59FJF
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-10
Last registration	2020-09-01
Complete history	See info



Registration #1	2009-12-10	7 mi
Registration #2	2012-10-26	68.494 mi
Registration #3	2013-11-05	93.353 mi
Registration #4	2014-11-13	117.050 mi
Registration #5	2014-11-14	117.050 mi
Registration #6	2015-11-06	141.067 mi
Registration #7	2015-11-13	141.465 mi
Registration #8	2016-11-10	165.089 mi
Registration #9	2016-11-10	165.089 mi
Registration #10	2016-11-10	165.089 mi
Registration #11	2016-11-10	165.089 mi
Registration #12	2016-11-10	165.089 mi
Registration #13	2016-11-10	165.089 mi
Registration #14	2016-11-10	165.089 mi
Registration #15	2016-11-10	165.089 mi
Registration #16	2016-11-10	165.089 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1625 kg
Max. allowed weight	2260 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	1AF5454242
---------------	------------