





report date: 2024-03-28

General information

| Make | VAUXHALL |
|---------------------|----------------------------|
| Model | MOVANO F3500 L3H2 P/V CDTI |
| Colour | Silver |
| Year of manufacture | 2015 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 1.500 rpm |
| Engine capacity | 2.299 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 41.5 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 184 g/km |
| CO2 label | 1 |



CarCheck.co.uk page 1/11



Internet history

| Entry | 1 |
|-------|---|
|-------|---|

| Date | 2021-07-16 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2022-06-08 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 2 |

| MOT #6 | 2021-06-09 09:55 |
|------------------|------------------|
| MOT test number | 347463344437 |
| Result | ✓ Passed |
| Next expiry date | 2022-06-08 |

| MOT #5 | 2020-06-06 07:05 |
|-----------------|------------------|
| MOT test number | 533577284255 |
| Result | ✓ Passed |

| MOT #4 | 2020-06-05 07:04 |
|-----------------|------------------|
| MOT test number | 939622600777 |

Result X Failed

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MAJOR Offside Front Drive shaft bearing excessively worn center support bearing (6.1.7 (b) (i))

| MOT #3 | 2019-05-07 12:25 |
|---|------------------|
| MOT test number | 297461457106 |
| Result | ✓ Passed |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

CarCheck.co.uk page 3/11



MOT #2

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1

MOT test number

220981971065

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Fail Nearside front brake application uneven nsf brake binding (3.7.B.2)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 4/11





Tax & MOT check

Tax expired: 1 July 2022



Expired: 8 June 2022 X MOT

Tax status Expired at 1 July 2022

Days left 668 days too late

MOT expiry date 8 June 2022

Full MOT history See MOT history

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date

Type Type

Damage 2

Date
Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. | |
|--|-------------|
| ******* | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| Plate changes | More info > |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | UK NE |
| Plate since | |
| Current registration | OK SIES |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2015-05-07 |
| Last registration | 2021-06-09 |
| Complete history | See info |



| Registration #1 | 2015-05-07 | 25 mi |
|-----------------|------------|------------|
| Registration #2 | 2018-05-11 | 111.622 mi |
| Registration #3 | 2018-05-11 | 111.623 mi |
| Registration #4 | 2019-05-07 | 118.803 mi |
| Registration #5 | | 9.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 90% |
| Pedestrian | 67% |
| Safety systems | 100% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 2470 mm |
|---------------------|---------|
| Height | 2488 mm |
| Length | 6198 mm |
| Kerb weight | 1970 kg |
| Max. allowed weight | 3500 kg |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | M9T -C017375 L0C |

CarCheck.co.uk page 11/11