





report date: 2024-03-29

General information

| Make | BMW |
|---------------------|-------------------------|
| Model | 435 435D XDRIVE M SPORT |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 155 mph |
| 0 - 60 mph | 4.7 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 308 BHP |
|-------------------------|---------------------|
| Max. torque | 630 Nm at 1.500 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 147 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2021-10-12

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-09-12

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-08-10

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-12-16 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 6 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #6 | 2023-12-14 10:50 |
|--|------------------|
| MOT test number | 290126968951 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-16 |
| Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #5 | 2022-12-16 11:38 |
|-----------------|------------------|
| MOT test number | 684147572367 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2021-12-17 13:54 |
| MOT test number | 177840561658 |
| Result | ✓ Passed |

| MOT #3 | 2020-12-15 08:42 |
|--|------------------|
| MOT test number | 587925016142 |
| Result | ✓ Passed |
| Advice Nearside front tyre slightly worn on the inner edge | |

CarCheck.co.uk page 3/11



report date: 2024-03-29

| MOT #2 | | 2019-11-02 10:20 |
|------------|---|------------------|
| MOT test i | number | 968216804093 |
| Result | | ✓ Passed |
| Advice | Brake disc worn, but not excessively rears (1.1.14 (a) (i)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #1 | 2018-09-27 08:44 |
|-----------------|------------------|
| MOT test number | 717546221696 |
| Result | √ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 16 December 2024

| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 216 |
| MOT expiry date | 16 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| \sim | | histo | |
|-----------|------|-------|----|
| - () () | vnor | nista | r٧ |
| | | | |

| For how long did the current and previous owner(s) have this BMW? How many owners did the check it in the premium report and see all owner registrations. Download the full report | | ve? |
|--|-----------|-----|
| | | |
| THE STATE OF THE S | | |
| | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this BMW had different number plates. | | |
| Number of plates | | |
| Current registration | UK NE | |
| Plate since | | |
| Current registration | UK UK | |
| Flate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-09-18 |
| Last registration | 2023-12-14 |
| Complete history | See info |



| Registration #1 | 2015-09-18 | 12 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-09-27 | 33.104 mi |
| Registration #3 | 2019-11-02 | 36.240 mi |
| Registration #4 | 2020-12-15 | 38.288 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1825 mm |
|---------------------|---------|
| Height | 1392 mm |
| Length | 4638 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1625 kg |
| Max. allowed weight | 2145 kg |

Additional information

| Fuel tank capacity | 57 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats CarCheck.co.uk | 4 page 11/1: |

Number of axles 2

Engine number 72159258