






report date: 2024-03-29

## General information

Make	JAGUAR
Model	XKR CONVERTIBLE
Colour	Green
Year of manufacture	2000
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.996 сс
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.4 mpg
Consumption combined	23.9 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

## Entry 1

Date	2022-01-11
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-03
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	20
Total items failed	25

MOT #21	2023-08-04 08:37
MOT test number	610338058945
Result	✓ Passed
Next expiry date	2024-08-03
Advice Nearside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	
Advice Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))	
Advice Offside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	

MOT #20	2020-12-03 12:47
MOT test number	917319422420
Result	✓ Passed

MOT #19	2019-07-11 11:54
MOT test number	142377517397
Result	✓ Passed
Advice Electronic stability control warning lamp not working (7.12 (e))	

MOT #18	2018-07-25 10:15
MOT test number	250627673677
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #17** 2017-07-26 15:02 **MOT** test number 207928913616 Result ✓ Passed **Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d) **Advice** Nearside Front Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e) Advice Coolant low Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.2b) **Advice** Front tyres need tracking

**MOT #16** 2017-07-25 10:55 361662896089 **MOT** test number Result ★ Failed **Advice** Nearside Front reflector damaged Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Offside Headlamp not working on main beam (1.7.5a) Fail Fail Offside Track rod end ball joint has excessive play (2.2.B.1f) Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.2b) Advice Coolant low Advice Front tyres need tracking Fail Nearside Headlamp aim too low (1.8) Advice Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d) Fail Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b)

MOT #15	2016-08-05 14:58
MOT test number	908605291570
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT #14** 2016-06-15 15:12 **MOT** test number 993832718431 Result **X** Failed Fail Nearside Rear Stop lamp not working (1.2.1b) Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Nearside Rear Lower Suspension arm has excessive play in a pin/bearing (2.4.G.2) Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Fail Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Front Lower Shock absorber has an excessively worn bush both (2.7.4) Rear registration plate insecure (6.3.1b) Fail Fail Front Upper Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt both (2.4.G.2) **Advice** Nearside Rear Sub-frame attachment slightly corroded rusty (2.4.G.1) Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) Nearside Rear Sub-frame rubber bush deteriorated resulting in excessive movement (2.4.G.2) Fail

MOT #13	2015-07-08 12:11
MOT test number	825089485120
Result	✓ Passed
Advice Offside Rear Rear position lamp(s) slightly discoloured (1.1.A.3e)	

MOT #12	2014-07-01 13:30
MOT test number	206532784184
Result	<b>✓</b> Passed
MOT #11	2013-07-17 16:39
MOT test number	195948993199
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #10	2013-07-17 13:00
MOT test number	238178093421
Result	<b>×</b> Failed
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail Nearside Windscreen washer provides insufficient washer liqu	uid (8.2.3)
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)	

MOT #9	2012-06-30 10:02
MOT test number	829252282109
Result	✓ Passed
Advice Nearside Headlamp damaged but light output not reduced (1.7.5a)	

MOT #8	2011-06-27 15:11
MOT test number	986988571102
Result	✓ Passed
MOT #7	2010-07-01 15:55
MOT test number	934202980106
Result	✓ Passed
MOT #6	2010-06-28 11:23
MOT test number	610719070159

MOT te	st number	610719070159
Result		🗙 Failed
Fail	Offside Front Side repeater missing (1.4.A.2b)	
Fail	Offside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #5

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #4
 2008-04-24 10:02

 MOT test number
 330305418115

 Result
 ✓ Passed

MOT test number

Result

Nearside Rear wheel bearing has excessive play (2.6.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)

Fail Offside Rear wheel bearing has excessive play (2.6.2)

MOT #2

MOT test number

481477207152

Result

Notice Offside front tyre edge worn slightly

Advice Front Shock absorber has a slightly worn bush (2.7.4)

MOT #1 2005-10-03 10:07

MOT test number 261926075266


Result ✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Tax & MOT check



Days left 277

MOT expiry date 3 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 8/13



report date: 2024-03-29

## Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this JAGUAR had different number plates. door of plates factor scincol

CarCheck.co.uk page 10/13



report date: 2024-03-29

## Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2000-10-25
Last registration	2023-08-04
Complete history	See info



Registration #1	2000-10-25	12 mi
Registration #2	2005-10-03	50.108 mi
Registration #3	2007-04-17	57.780 mi
Registration #4	2008-04-21	62.677 mi
Registration #5	2008-04-24	62.717 mi
Registration #6	2009-07-01	66.570 mi
Registration #7	2010-06-28	69.971 mi
Registration #8	2010-07-01	69.985 mi
Registration #9	2011-06-27	71.753 mi
Registration #10	2012-06-30	75.440 mi
Registration #11	2013-07-17	80.397 mi
Registration #12	2013-07-17	80.401 mi
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		0.70 es
Registration #18		11.777 es
Registration #19		0.70 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		

More info >

CarCheck.co.uk page 12/13



X409NBW report date: 2024-03-29

			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	2015 mm
Height	1306 mm
Length	4760 mm
Wheel base	2588 mm

# Additional information

Fuel tank capacity	75 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	NB0012020817

CarCheck.co.uk page 13/13