



report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Grey
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	313 BHP
Max. torque	700 Nm at 1.500 rpm
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-20
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #14</b>	2021-11-11 14:45
<b>MOT test number</b>	254948319951
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-11-10

<b>MOT #13</b>	2021-11-10 11:20
<b>MOT test number</b>	235164993457
<b>Result</b>	✗ Failed

**Fail** Offside Rear Anti-roll bar linkage ball joint likely to become detached has detached (5.3.4 (a) (ii))

**Advice** Brake pad(s) wearing thin rear pads (1.1.13 (a) (ii))

**Advice** Rear seatbelts cannot be checked, seats down with heavy parcel on top

**Fail** Nearside Rear Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))

**Advice** Brake pad(s) wearing thin front pads (1.1.13 (a) (ii))

<b>MOT #12</b>	2021-05-28 08:48
<b>MOT test number</b>	704183301139
<b>Result</b>	✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #11</b>	2021-05-27 13:19
<b>MOT test number</b>	921609749762
<b>Result</b>	✗ Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Rear Nail in tyre

**MOT #10** 2020-06-16 14:18**MOT test number** 680649583513**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2020-06-16 09:06**MOT test number** 460338123318**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2019-05-21 10:02**MOT test number** 567380403042**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2019-05-17 11:03**MOT test number** 432874869599**Result** ✗ Failed**Fail** Nearside Rear Suspension arm ball joint excessively worn Rear arm (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm ball joint has slight play Rear arm (5.3.4 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn Front arm (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2018-06-14 10:47**MOT test number** 303658478013**Result** ✓ Passed**MOT #5** 2017-06-17 09:40**MOT test number** 133861475086**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-06-16 13:05**MOT test number** 261964033350**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2016-05-19 12:32
MOT test number	506260420755
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice	Offside Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #2	2015-06-15 12:57
MOT test number	126216265177
Result	✓ Passed

MOT #1	2014-06-17 12:49
MOT test number	168508364180
Result	✓ Passed



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-31
Last registration	2021-11-11
Complete history	<a href="#">See info</a>



Registration #1	2011-05-31	25 mi
Registration #2	2014-06-17	39.453 mi
Registration #3	2015-06-15	53.544 mi
Registration #4	2016-05-19	70.045 mi
Registration #5	2017-06-16	87.053 mi
Registration #6	2017-06-17	87.055 mi
Registration #7	2018-06-14	96.861 mi
Registration #8	2019-05-17	106.624 mi
Registration #9	2020-05-20	121.377 mi
Registration #10	2020-05-20	121.377 mi
Registration #11	2020-05-20	121.377 mi
Registration #12	2020-05-20	121.377 mi
Registration #13	2020-05-20	121.377 mi
Registration #14	2020-05-20	121.377 mi
Registration #15	2020-05-20	121.377 mi
Registration #16	2020-05-20	121.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT