



BV070UU

report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE D XS
Colour	Black
Year of manufacture	-
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg






Internet history

Entry 2

Date	2022-08-25
Pictures	18
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-18
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #20	2021-11-12 15:41
MOT test number	640958626150
Result	✓ Passed
Next expiry date	2022-11-12
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Coolant leak
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #19	2020-11-09 14:05
MOT test number	154322065701
Result	✓ Passed

MOT #18	2019-11-05 10:19
MOT test number	228817253990
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #17**

2019-11-04 15:09

MOT test number

413346041505

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Fail Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #16

2018-11-13 11:26

MOT test number

375647373146

Result**✓ Passed****MOT #15**

2018-11-07 17:03

MOT test number

753149606696

Result**✗ Failed**

- Fail** Horn not working (7.7 (a) (ii))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))
- Minor** Offside Rear Outer Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed split (5.2.3 (d) (ii))

MOT #14

2017-11-09 16:56

MOT test number

313518914434

Result**✓ Passed**

**MOT #13**

2017-11-04 09:06

MOT test number

150913093982

Result

✗ Failed

Fail Brake servo leaking (3.6.C.1c)**Fail** Nearside Rear Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Battery insecure (1.9.1)**Fail** Offside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #12**

2016-10-02 10:02

MOT test number

195150543898

Result

✓ Passed

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Washers weak effort**MOT #11**

2015-10-08 13:03

MOT test number

553793333216

Result

✓ Passed

MOT #10

2015-10-08 10:15

MOT test number

973221450050

Result

✗ Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement inner (2.4.G.2)

**MOT #9** 2015-09-27 13:14**MOT test number** 427547930289**Result** ✗ Failed

- Advice** Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** No emissions detected
- Advice** Road wheel slightly damaged all (4.2.A.1a)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Sill and underbody covers fitted

MOT #8 2014-10-29 08:48**MOT test number** 615052104309**Result** ✓ Passed**MOT #7** 2014-04-18 13:01**MOT test number** 897298204191**Result** ✓ Passed

- Advice** Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Under-trays fitted obscuring some underside components

**MOT #6** 2014-04-18 10:54**MOT test number** 477048304195**Result** ✗ Failed**Fail** Nearside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Offside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #5** 2013-04-02 17:05**MOT test number** 178212193044**Result** ✓ Passed**MOT #4** 2012-05-02 09:06**MOT test number** 159283622109**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** O/s/f and both rear wheels damaged on inner**MOT #3** 2011-05-16 10:38**MOT test number** 657836031128**Result** ✓ Passed



MOT #2	2010-05-18 12:02
MOT test number	213228530112
Result	✓ Passed
MOT #1	2010-03-16 13:04
MOT test number	411585770080
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-17
Last registration	2021-11-12
Complete history	See info



Registration #1	2007-03-17	22 mi
Registration #2	2010-03-16	55.934 mi
Registration #3	2010-05-18	56.222 mi
Registration #4	2011-05-16	62.444 mi
Registration #5	2012-05-02	67.494 mi
Registration #6	2013-04-02	71.922 mi
Registration #7	2014-04-18	75.050 mi
Registration #8	2014-04-18	75.050 mi
Registration #9	2014-10-29	75.957 mi
Registration #10	2015-09-27	77.240 mi
Registration #11	2015-10-08	77.259 mi
Registration #12	2015-10-08	77.259 mi
Registration #13	2015-10-08	77.259 mi
Registration #14	2015-10-08	77.259 mi
Registration #15	2015-10-08	77.259 mi
Registration #16	2015-10-08	77.259 mi
Registration #17	2015-10-08	77.259 mi
Registration #18	2015-10-08	77.259 mi
Registration #19	2015-10-08	77.259 mi
Registration #20	2015-10-08	77.259 mi
Registration #21	2015-10-08	77.259 mi
Registration #22	2015-10-08	77.259 mi
Registration #23	2015-10-08	77.259 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	02224317G