





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.5 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 104 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-12-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-09
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #13	2023-11-10 12:05
MOT test number	639490188286
Result	√ Passed
Next expiry date	2024-11-09
Advice Topped up engine oil prior to test	

MOT #12	2023-10-28 08:21
MOT test number	789184937327
Result	🗙 Failed
Fail Rear fog lamp not working bulb holder missing & wiring damaged (4.5.1 (a) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Topped up engine oil prior to test	

MOT #11		2022-12-13 12:01
MOT test	number	509572402747
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #7

LY62ASO

report date: 2024-03-29

2019-12-10 12:35

MOT #10 2022-12-09 14:56 802997290178 **MOT** test number Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e)) Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #9

MOT test number

191335456265

Result

Advice Coolant level below min

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

MOT test number

764759776350

Result

✓ Passed

MOT test number 594531078606

Result Passed

MOT #6 2019-12-10 12:02

MOT test number 497474055355

Result × Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



LY62ASO

report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Slight play in steering wheel

MOT test number

328149623765

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Slight play in steering wheel

MOT test number

Result

Advice
Nearside Rear Tyre has large cut in thread, Unable to see cords at time of test

Wipers smear

Advice wipers smear	
MOT #2	2016-12-16 10:35
MOT test number	911611545229
Result	✓ Passed
MOT #1	2015-12-17 14:30
MOT test number	251454055603
Result	✓ Passed
Advice Under tray fitted	

CarCheck.co.uk page 5/12



Tax & MOT check



✓ MOT

Tax expired: 2 April 2024

Expires: 9 November 2024

Tax status	Expired at 2 April 2024
Days left	28 days too late
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-02-08
Last registration	2023-11-10
Complete history	See info



Registration #1	2013-02-08	29 mi
Registration #2	2015-12-17	6.904 mi
Registration #3	2016-12-16	14.057 mi
Registration #4	2017-12-07	19.425 mi
Registration #5	2018-12-04	22.795 mi
Registration #6	2018-12-04	22.795 mi
Registration #7	2019-12-10	24.776 mi
Registration #8	2019-12-10	24.776 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.117 es
Registration #12		11.117 es
Registration #13		11.117 es
Registration #14		0.00 44
Registration #15		9.77 ss

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1274 kg
Max. allowed weight	1860 kg

Additional information

Production of the state of the	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12