





report date: 2024-03-29

## General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	Red
Year of manufacture	2014
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

E ~	+	, 1
	ILI V	, .

Entry 1	
Date	2021-02-04
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #10	2024-04-02 12:49
MOT test number	374179489529
Result	✓ Passed
Next expiry date	2025-04-01

MOT #9	2023-03-01 16:03
MOT test number	115126892029
Result	✓ Passed

MO1 #8	2023-02-28 10:55
MOT test number	215192090999

**Result** X Failed

**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #7	2022-02-28 17:06
MOT test number	945177659018
Result	✓ Passed

CarCheck.co.uk page 3/11



FM14AXA

report date: 2024-03-29

MOT #6 2021-03-26 17:06

**MOT test number** 723867189786

MOT #5 2020-12-24 11:11

**MOT test number** 992239872625

Result 

Passed

MOT #4 2019-06-13 15:13

MOT test number 853254251661

**Result** 
✓ Passed

MOT #3 2019-06-13 15:13

**MOT test number** 439877933478

Result X Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Pass with rectification** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Pass with rectification Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #2 2018-05-30 13:23

**MOT test number** 790277711649

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge ACTUALLY ON LOWER WEAR LIMIT OF

1.6mm OF TREAD IN PLACES - ADVISE REPLACEMENT IN VERY NEAR FUTURE (5.2.3 (e))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2017-06-06 12:10

MOT test number 965482428336

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
THE STATE OF THE S	
***************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	NIEZ ZIN UK
Plate since	
Current registration	RK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-08-19
Last registration	2024-04-02
Complete history	See info



Registration #1	2014-08-19	6 mi
Registration #2	2017-06-06	20.363 mi
Registration #3	2018-05-30	29.219 mi
Registration #4	2019-06-13	41.333 mi
Registration #5	2019-06-13	41.333 mi
Registration #6	2020-12-24	51.897 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



# Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

# Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1827015

CarCheck.co.uk page 11/11