



R19KBM

report date: 2024-03-29

General information

| | |
|---------------------|------------------------------------|
| Make | VOLKSWAGEN |
| Model | SCIROCCO TDI BLUEMOTION TECHNOLOGY |
| Colour | Blue |
| Year of manufacture | 2013 |
| Top speed | 129 mph |
| 0 - 60 mph | 9.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 140 BHP |
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 118 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-03 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-29 |
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 22 |
| Total items failed | 3 |

| | |
|---------|------------------|
| MOT #12 | 2023-07-28 14:19 |
|---------|------------------|

| | |
|-----------------|--------------|
| MOT test number | 726083752095 |
|-----------------|--------------|

| | |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

| | |
|------------------|------------|
| Next expiry date | 2024-07-29 |
|------------------|------------|

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #11**

2023-07-28 10:55

MOT test number

865821011123

Result**✗ Failed**

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Nail in tyre
- MAJOR** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Offside Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10

2022-07-04 16:13

MOT test number

930936162218

Result**✓ Passed**

- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #9

2022-07-04 09:22

MOT test number

792177077173

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps x 2 (4.7.1 (b) (ii))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #8** 2021-07-29 12:19**MOT test number** 912245609868**Result** ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2020-07-30 09:49**MOT test number** 124948589633**Result** ✓ Passed**MOT #6** 2019-05-15 08:21**MOT test number** 761387463236**Result** ✓ Passed

Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #5 2018-10-26 14:43**MOT test number** 753496562926**Result** ✓ Passed**MOT #4** 2018-10-23 13:39**MOT test number** 916275717937**Result** ✗ Failed

DANGEROUS Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

DANGEROUS Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #3 2017-10-20 16:16**MOT test number** 335760965989**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #2 | 2017-10-20 11:12 |
| MOT test number | 143149221869 |
| Result | ✗ Failed |
| Fail | Nearside Rear Registration plate lamp not working (1.1.C.1d) |
| Fail | Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) |

| | |
|-----------------|------------------|
| MOT #1 | 2016-10-01 09:24 |
| MOT test number | 655924599466 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
29 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 29 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,200 |
| Auction value | £ 19,200 |
| Average private trade value | £ 19,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2013-10-08 |
| Last registration | 2023-07-28 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-10-08 | 15 mi |
| Registration #2 | 2016-10-01 | 61.403 mi |
| Registration #3 | 2017-10-20 | 69.583 mi |
| Registration #4 | 2017-10-20 | 69.592 mi |
| Registration #5 | 2018-10-23 | 80.520 mi |
| Registration #6 | 2018-10-26 | 80.538 mi |
| Registration #7 | 2019-05-15 | 82.568 mi |
| Registration #8 | 2019-05-15 | 82.577 mi |
| Registration #9 | 2019-05-15 | 82.577 mi |
| Registration #10 | 2019-05-15 | 82.577 mi |
| Registration #11 | 2019-05-15 | 82.577 mi |
| Registration #12 | 2019-05-15 | 82.577 mi |
| Registration #13 | 2019-05-15 | 82.577 mi |
| Registration #14 | 2019-05-15 | 82.577 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1404 mm |
| Length | 4256 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1318 kg |
| Max. allowed weight | 1750 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | CFHC520511 |