



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-05
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #15</b>	2021-07-08 10:27
<b>MOT test number</b>	885175656047
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-07-07
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

<b>MOT #14</b>	2020-06-16 09:54
<b>MOT test number</b>	353511466554
<b>Result</b>	✓ Passed
<b>Advice</b>	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

<b>MOT #12</b>	2018-07-03 11:28
<b>MOT test number</b>	303566119323
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2018-07-03 11:28
<b>MOT test number</b>	456675002676
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

<b>MOT #10</b>	2017-07-03 09:23
<b>MOT test number</b>	771151935128
<b>Result</b>	✓ Passed

**MOT #9**

2016-07-01 10:34

**MOT test number**

142481111342

**Result**

✓ Passed

**Advice** Offside Front Macpherson strut has slight movement at the upper attachment top mount slight play (2.5.A.1c)

**Advice** Offside Front Lower Bonded suspension unit deteriorated but can function as intended wishbone bush splitting (2.4.F.3)

**Advice** Offside Front Upper Direction indicator damaged, but still visible from a reasonable distance Mirror indicator cracked (1.4.A.2e)

**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment top mount slight play (2.5.A.1c)

**Advice** Nearside Front Lower Bonded suspension unit deteriorated but can function as intended wishbone bush splitting (2.4.F.3)

**Advice** Centre Rear Stop lamp has light sources not illuminating, but not more than 50% 3rd brake lamp 1x LED out (1.2.1b)

**Advice** Offside Rear Tyre worn close to the legal limit 2mm on contact surface (4.1.E.1)

**MOT #8**

2015-07-04 15:15

**MOT test number**

135215085183

**Result**

✓ Passed

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2015-07-04 10:25

**MOT test number**

227035285431

**Result**

✗ Failed

**Fail** Centre Front Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6**

2014-07-04 17:12

**MOT test number**

138505284129

**Result**

✓ Passed





<b>MOT #5</b>	2013-07-06 11:49
---------------	------------------

<b>MOT test number</b>	958867983120
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2012-05-09 11:55
---------------	------------------

<b>MOT test number</b>	937340732125
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2011-05-09 14:56
---------------	------------------

<b>MOT test number</b>	935869321189
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2010-07-07 14:54
---------------	------------------

<b>MOT test number</b>	811148180134
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>MOT #1</b>	2009-06-30 11:38
---------------	------------------

<b>MOT test number</b>	651651889199
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-07-01
Last registration	2021-07-08
Complete history	<a href="#">See info</a>



Registration #1	2006-07-01	14 mi
Registration #2	2009-06-30	25.652 mi
Registration #3	2010-07-07	36.908 mi
Registration #4	2011-05-09	42.710 mi
Registration #5	2012-05-09	51.085 mi
Registration #6	2013-07-06	61.310 mi
Registration #7	2014-07-04	69.269 mi
Registration #8	2015-07-04	77.331 mi
Registration #9	2015-07-04	77.331 mi
Registration #10	2016-06-29	85.377 mi
Registration #11	2017-06-29	93.423 mi
Registration #12	2018-06-29	101.469 mi
Registration #13	2019-06-29	109.515 mi
Registration #14	2020-06-29	117.561 mi
Registration #15	2021-06-29	125.607 mi
Registration #16	2022-06-29	133.653 mi
Registration #17	2023-06-29	141.699 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 051011