





report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 E-HDI ACTIVE
Colour	Black
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	14.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history


Entry 1


Date 2021-11-25

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-07
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	9

MOT #12	2023-11-17 15:32
MOT test number	841649656724
Result	✓ Passed
Next expiry date	2024-12-07

MOT #3	11	2023-11-17 14:29
MOT te	st number	801390854088
Result		X Failed
Fail	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #10	2022-11-28 15:2
MOT test	number 68761287358.
Result	✓ Passe
Advice Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e)) Nearside Front Tyre worn close to legal limit/worn on edge Close to ply and cord layer (5.2.3 (e))

CarCheck.co.uk page 3/13



Fail

CF13HHD

report date: 2024-03-28

MOT #9 2022-11-25 13:46 **MOT** test number 835548226005 Result × Failed Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e)) Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail **Minor** Nearside Front Tyre obviously under inflated (5.2.3 (I)) Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Nearside Front Tyre worn close to legal limit/worn on edge Close to ply and cord layer (5.2.3 (e)) **Advice** Fail Offside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i)) **Minor** Offside Front Tyre obviously under inflated (5.2.3 (I))

MOT #8	2021-12-08 15:02
MOT test number	125817222123
Result	✓ Passed
MOT #7	2021-12-06 15:46
MOT test number	825481536567

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Result × Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Play in steering rack inner joint(s)

Advice Slight smearing to wipers

Advice Nearside Rear Brake pad(s) wearing thin on limits (1.1.13 (a) (ii))

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor (b) (i))

Mor test number

149167764801

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2018-04-30 12:41
MOT test number	888931368112
Result	✓ Passed
MOT #2	2017-05-08 09:20
MOT test number	243015510038
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1

MOT test number

852985382475

Result

Advice Unable to detect emissions on test

CarCheck.co.uk page 6/13



Tax & MOT check





Expires: 7 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13




report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

CF13HHD

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-30
Last registration	2023-11-17
Complete history	See info



Registration #1	2013-06-30	26 mi
Registration #2	2016-05-09	30.546 mi
Registration #3	2017-05-08	36.949 mi
Registration #4	2018-04-30	44.626 mi
Registration #5	2019-05-07	50.344 mi
Registration #6	2020-05-04	53.350 mi
Registration #7	2021-04-19	56.055 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1837 mm
Height	1640 mm
Length	4365 mm
Wheel base	2613 mm
Kerb weight	1626 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/3

Number of axles 2

Engine number JBFT3004926