



PEUGEOT



DE58EFR

report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 VERVE
Colour	Red
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F





## Internet history

### Entry 4

Date 2021-07-30

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date 2021-07-16

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date 2021-07-02

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date 2021-05-23

CarCheck.co.uk

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2023-03-06
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	12

MOT #16	2022-03-07 15:37
MOT test number	312732783954
Result	✓ Passed
Next expiry date	2023-03-06

MOT #15	2022-02-23 12:41
MOT test number	704292795221
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Road wheel fixing missing 4 x (5.2.1 (a) (i))
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #14	2021-01-18 09:26
MOT test number	795624217933
Result	✓ Passed

**MOT #13** 2021-01-12 12:02**MOT test number** 393321564615**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2019-06-29 16:37**MOT test number** 582687148513**Result** ✓ Passed**MOT #11** 2019-01-24 10:48**MOT test number** 349790655101**Result** ✓ Passed**MOT #10** 2018-01-18 11:01**MOT test number** 548591187835**Result** ✓ Passed**MOT #9** 2018-01-18 11:01**MOT test number** 245150889718**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #8** 2017-01-26 15:04**MOT test number** 487081832791**Result** ✓ Passed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2017-01-26 09:45**MOT test number** 158730781404**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2016-01-26 14:56**MOT test number** 899280293707**Result** ✓ Passed**MOT #5** 2015-01-31 13:00**MOT test number** 955121035056**Result** ✓ Passed**MOT #4** 2014-01-15 10:50**MOT test number** 116875214478**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak



MOT #3	2014-01-15 10:50
MOT test number	766875114054
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)
Notice	Oil leak
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-01-17 10:51
MOT test number	116467613081
Result	✓ Passed
Notice	Rear exhaust bracket broken but system supported
Notice	Oil leak

MOT #1	2012-01-17 09:21
MOT test number	169097212010
Result	✓ Passed



Tax & MOT check

✕  
**Untaxed**

**Tax expired:**  
24 December 2021

✕  
**MOT**

**Expired:**  
6 March 2023

<b>Tax status</b>	Expired at 24 December 2021
<b>Days left</b>	856 days too late
<b>MOT expiry date</b>	6 March 2023
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	DE58EFR
Plate since	2019-03-28
Current registration	DE58EFR
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-01-28
Last registration	2022-03-07
Complete history	<a href="#">See info</a>



Registration #1	2009-01-28	26 mi
Registration #2	2012-01-17	19.671 mi
Registration #3	2013-01-17	30.962 mi
Registration #4	2014-01-15	42.477 mi
Registration #5	2015-01-31	53.600 mi
Registration #6	2016-01-26	57.508 mi
Registration #7	2017-01-26	61.975 mi
Registration #8	2017-01-26	61.975 mi
Registration #9	2018-01-18	66.283 mi
Registration #10	2018-01-18	66.283 mi
Registration #11	2019-01-28	66.283 mi
Registration #12	2019-01-28	66.283 mi
Registration #13	2019-01-28	66.283 mi
Registration #14	2019-01-28	66.283 mi
Registration #15	2019-01-28	66.283 mi
Registration #16	2019-01-28	66.283 mi
Registration #17	2019-01-28	66.283 mi
Registration #18	2019-01-28	66.283 mi
Registration #19	2019-01-28	66.283 mi
Registration #20	2019-01-28	66.283 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1213 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FST36005359