



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Grey
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	165 g/km
CO2 label	G





MOT history

MOT expiry date	2025-04-06
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	76
Total items failed	28

MOT #25	2024-04-04 15:44
MOT test number	756064103640
Result	✓ Passed
Next expiry date	2025-04-06
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #24**

2024-04-03 10:31

MOT test number

798771398555

Result**✗ Failed**

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure 185x60x14 (5.2.3 (d) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Fail Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Side repeater missing (4.4.1 (a) (ii))

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Direction indicator light intensity significantly reduced (4.4.3 (a))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Headlamp are incorrectly positioned (4.1.4 (a))

MOT #23

2023-04-07 15:21

MOT test number

394964505784

Result**✓ Passed**

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Front Brake pad(s) wearing thin Both (1.1.13 (a) (ii))

Advice Front Suspension component pin or bush slightly worn Both (5.3.4 (a) (i))

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

**MOT #22**

2023-04-07 11:08

MOT test number

503482618973

Result**✗ Failed**

- Advice** Front Suspension component pin or bush slightly worn Both (5.3.4 (a) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin Both (1.1.13 (a) (ii))

MOT #21

2022-05-17 14:26

MOT test number

414235014884

Result**✓ Passed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #20

2021-05-20 13:21

MOT test number

230650449016

Result**✓ Passed****MOT #19**

2020-10-02 11:58

MOT test number

557206605231

Result**✓ Passed**

**MOT #18**

2019-04-03 10:54

MOT test number

563903301215

Result

✓ Passed

Advice

Offside Play in steering rack inner joint(s)

Advice

Nearside Rear Light lens damaged.

Minor

Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #17

2018-04-04 10:26

MOT test number

605095951675

Result

✓ Passed

Advice

Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Advice

Engine management light on dash

Advice

Nearside Front tyre worn on inner edge

Advice

Nearside Rear light unit broken

Advice

Oil leak

Advice

Offside Front Inner steering arm has slight movement at its fixings

Advice

Service light on

Advice

Nearside wing mirror casing slightly damaged

**MOT #16**

2018-04-03 12:00

MOT test number

299767854359

Result**✗ Failed**

- Advice** Nearside Rear light unit broken
- Advice** Offside Front Inner steering arm has slight movement at its fixings
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Service light on
- Fail** Central Lower engine mounting deteriorated resulting in excessive movement stabilizer (6.1.D.1a)
- Advice** Nearside wing mirror casing slightly damaged
- Advice** Engine management light on dash
- Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Nearside Front tyre worn on inner edge
- Advice** Oil leak

MOT #15

2017-03-17 17:44

MOT test number

467531620974

Result**✓ Passed**

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush Rear bush. (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush Rear bush. (2.4.G.2)

**MOT #14**

2017-03-17 09:34

MOT test number

866389624110

Result**✗ Failed****Fail** Nearside Front Tyre has ply or cords exposed Tyre sidewall damaged exposing cords. (4.1.D.1b)**Advice** Items removed from driver's view prior to test**Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush Rear bush. (2.4.G.2)**Fail** Rear brake application uneven (3.7.B.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush Rear bush. (2.4.G.2)**MOT #13**

2016-04-02 13:56

MOT test number

654380266642

Result**✓ Passed****Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #12**

2016-04-02 10:17

MOT test number

714880788881

Result**✗ Failed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Coolant slightly below minimum**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 185/60/14 (4.1.E.1)**Fail** Offside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #11** 2015-06-05 09:31**MOT test number** 766016355184**Result** ✓ Passed**Notice** Nearside rear lamp cracked.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2015-06-05 09:31**MOT test number** 865456155115**Result** ✗ Failed**Notice** Nearside rear lamp cracked.**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #9** 2014-06-09 12:07**MOT test number** 798760764154**Result** ✓ Passed**Notice** Nearside rear light unit broken**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components



MOT #8	2014-06-09 12:07
MOT test number	339730864131
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Nearside rear light unit broken
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Notice	Under-trays fitted obscuring some underside components

MOT #7	2013-06-10 16:16
MOT test number	479591463136
Result	✓ Passed
Notice	Both front lower arm rear bushes have slight movement
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Nearside rear side light lense cover broken
Notice	Under-trays fitted obscuring some underside components
Advice	Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #6**

2013-06-10 10:07

MOT test number

529231263180

Result**✗ Failed**

- Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)
- Notice** Nearside rear side light lense cover broken
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Both front lower arm rear bushes have slight movement
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Notice** Both front tyres wearing close to legal limit
- Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5

2012-09-26 16:09

MOT test number

305520172227

Result**✓ Passed**

- Notice** Nearside rear light lense loose
- Notice** Both front brake disc heavily worn
- Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Notice** Both front lower rear bush has slight movement



MOT #4 2012-09-26 16:09

MOT test number 758270272237

Result ✗ Failed

Pass with rectification Offside Front Direction indicators not working (1.4.A.2c)

Notice Nearside rear light lense loose

Notice Both front brake disc heavily worn

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Both front lower rear bush has slight movement

MOT #3 2011-09-19 13:23

MOT test number 507602761279

Result ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2010-09-23 12:43

MOT test number 373616860291

Result ✓ Passed

MOT #1 2010-04-28 14:33

MOT test number 534678610143

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
6 April 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL07GOH
Plate since	2024-03-29
Current registration	 GL07GOH
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-06-26
Last registration	2024-04-04
Complete history	See info



Registration #1	2007-06-26	16 mi
Registration #2	2010-04-28	23.116 mi
Registration #3	2010-09-23	27.238 mi
Registration #4	2011-09-19	33.475 mi
Registration #5	2012-09-26	41.615 mi
Registration #6	2013-06-10	46.196 mi
Registration #7	2013-06-10	46.196 mi
Registration #8	2014-06-09	53.852 mi
Registration #9	2015-06-05	62.441 mi
Registration #10	2016-04-02	70.467 mi
Registration #11	2016-04-02	70.467 mi
Registration #12	2017-03-17	76.959 mi
Registration #13	2018-03-20	85.377 mi
Registration #14	2018-03-20	85.377 mi
Registration #15	2018-03-20	85.377 mi
Registration #16	2018-03-20	85.377 mi
Registration #17	2018-03-20	85.377 mi
Registration #18	2018-03-20	85.377 mi
Registration #19	2018-03-20	85.377 mi
Registration #20	2018-03-20	85.377 mi
Registration #21	2018-03-20	85.377 mi
Registration #22	2018-03-20	85.377 mi
Registration #23	2018-03-20	85.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1770 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BUD 077170