



report date: 2024-03-28

## General information

Make	VOLVO
Model	V70 D3 SE
Colour	Black
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-14
Pictures	38
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-29
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	31
Total items failed	0

MOT #14	2023-12-18 09:10
MOT test number	794924837863
Result	✓ Passed
Next expiry date	2024-12-29
Advice	Front brake discs corroded & lipped
Advice	Wipers smear

MOT #13	2022-12-02 12:07
MOT test number	420874840405
Result	✓ Passed
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #12	2022-12-01 10:44
MOT test number	450191289643
Result	✗ Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #11**

2021-12-30 14:11

**MOT test number**

625290956277

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))**MOT #10**

2021-12-29 13:45

**MOT test number**

913127743984

**Result**

✗ Failed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 2255017 (5.2.3 (d) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #9**

2020-12-26 15:36

**MOT test number**

623646262740

**Result**

✓ Passed

**MOT #8**

2019-05-02 15:41

**MOT test number**

623858192770

**Result**

✓ Passed

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #7** 2019-04-23 10:59**MOT test number** 180431954076**Result** ✗ Failed

- MAJOR** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm ( front bush ) (5.3.4 (a) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm ( front bush ) (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #6** 2018-05-01 12:42**MOT test number** 860890890347**Result** ✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #5** 2017-05-19 08:01**MOT test number** 954702182039**Result** ✓ Passed**MOT #4** 2016-09-15 08:23**MOT test number** 367767954776**Result** ✓ Passed

- Advice** Offside Play in steering rack inner joint(s)



MOT #3	2015-09-03 14:20
MOT test number	781353799633
Result	✓ Passed
Advice	Offside steering track rod has slight play in inner joint (drumstick)

MOT #2	2014-09-05 14:03
MOT test number	476048744220
Result	✓ Passed

MOT #1	2013-09-16 11:12
MOT test number	128579253231
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
29 December 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	29 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-17
Last registration	2023-12-18
Complete history	<a href="#">See info</a>



Registration #1	2010-09-17	27 mi
Registration #2	2013-09-16	10.960 mi
Registration #3	2014-09-05	16.453 mi
Registration #4	2015-09-03	23.181 mi
Registration #5	2016-09-15	28.313 mi
Registration #6	2017-05-19	30.376 mi
Registration #7	2018-05-01	38.099 mi
Registration #8	2019-04-23	44.819 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2021-05-20	65.277 mi
Registration #11	2022-05-20	75.277 mi
Registration #12	2023-05-20	85.277 mi
Registration #13	2024-05-20	95.277 mi
Registration #14	2025-05-20	105.277 mi
Registration #15	2026-05-20	115.277 mi
Registration #16	2027-05-20	125.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1643 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

870929