





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 T-GDI SE NAV
Colour	Beige
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2024-04-20

Pictures 39

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-03-09
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



WU18BKD report date: 2024-03-29

MOT history

MOT expiry date	2025-04-04
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5		2024-03-20 15:01
MOT test	number	596400144113
Result		✓ Passed
Next expi	ry date	2025-04-04
Advice	Windscreen cracked	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a)) (i))
Advice	Nearside Rear Brake slightly binding	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2023-03-30 13:45
MOT test number	116387077602
Result	✓ Passed
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Items removed from driver's view prior to test	

MOT #3	2022-04-05 14:21
MOT test number	245056448156
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2021-03-23 13:27

MOT test number 118926608654

Result ✓ Passed

MOT #1 2021-03-23 09:11

MOT test number 488870607738

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge soon will show cords (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge soon will show cords (5.2.3 (e))

Advice Offside Rear Nail in tyre

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check

Tax expired: 11 April 2024





Tax status	Expired at 11 April 2024
Days left	18 days too late
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here .	

HARMAN CO.	

Plate changes	More info >
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-29
Last registration	2024-03-20
Complete history	See info



Registration #1	2018-03-29	22 mi
Registration #2	2021-03-23	35.157 mi
Registration #3	2021-03-23	35.158 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1425 mm
Length	4455 mm
Wheel base	2650 mm
Kerb weight	1342 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine numberG3LCJP021400