



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC AUTHENTIQUE 16V G/SCENIC
Colour	Silver
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-03
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	15
Total items failed	16

MOT #22	2023-09-04 09:29
MOT test number	691365164065
Result	✓ Passed
Next expiry date	2024-09-26
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #21	2022-09-27 07:45
MOT test number	635490645143
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material both main centre (1.1.11 (c))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2022-09-17 11:36

MOT test number

229358480614

Result**✗ Failed****Advice**

Brake pipe corroded, covered in grease or other material both main centre (1.1.11 (c))

Fail

Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail

Offside Front Tyre has ply or cords exposed cracking cords visible (5.2.3 (d) (ii))

Fail

Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Fail

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail

Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

Fail

Nearside Front Obligatory mirror insecure (3.3 (b) (ii))

Fail

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #19

2021-09-06 12:18

MOT test number

150183511708

Result**✓ Passed****MOT #18**

2021-01-21 16:35

MOT test number

385160069161

Result**✓ Passed****MOT #17**

2018-03-13 12:49

MOT test number

403757005548

Result**✓ Passed**

**MOT #16** 2018-03-13 09:28**MOT test number** 507054845147**Result** ✗ Failed**Fail** Nearside Rear Exhaust system not adequately supported (7.1.1)**Fail** Central Exhaust system not adequately supported (7.1.1)**Fail** Steering wheel in a condition that hampers proper control (2.1.1)**MOT #15** 2017-03-14 11:22**MOT test number** 617352463265**Result** ✓ Passed**MOT #14** 2016-03-09 14:41**MOT test number** 122585292734**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #13** 2015-04-01 11:13**MOT test number** 645591495028**Result** ✓ Passed**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #12** 2015-04-01 11:13**MOT test number** 498281395089**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #11** 2014-10-22 11:02**MOT test number** 339085794257**Result** ✓ Passed**MOT #10** 2014-10-22 11:02**MOT test number** 587085294217**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #9** 2013-10-23 11:44**MOT test number** 355146593409**Result** ✓ Passed**MOT #8** 2013-10-23 11:44**MOT test number** 905256293272**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)

**MOT #7** 2012-10-24 11:16**MOT test number** 308848092486**Result** ✓ Passed**Notice** Rear tyres starting to perish**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2011-10-20 10:49**MOT test number** 349553591244**Result** ✓ Passed**MOT #5** 2011-10-20 10:49**MOT test number** 878763791280**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2010-10-15 09:47**MOT test number** 331678280408**Result** ✓ Passed**MOT #3** 2009-10-29 17:46**MOT test number** 743632109317**Result** ✓ Passed**MOT #2** 2009-06-01 09:03**MOT test number** 792042259178**Result** ✓ Passed**MOT #1** 2008-06-04 12:09**MOT test number** 423216858106**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-06
Last registration	2023-09-04
Complete history	See info



Registration #1	2005-07-06	14 mi
Registration #2	2008-06-04	23.326 mi
Registration #3	2009-06-01	29.742 mi
Registration #4	2009-10-29	31.682 mi
Registration #5	2010-10-15	43.129 mi
Registration #6	2011-10-20	54.772 mi
Registration #7	2012-10-24	67.121 mi
Registration #8	2013-10-23	4.208 mi
Registration #9	2014-10-22	17.846 mi
Registration #10	2015-04-01	23.481 mi
Registration #11	2015-05-20	25.277 mi
Registration #12	2015-05-20	25.277 mi
Registration #13	2015-05-20	25.277 mi
Registration #14	2015-05-20	25.277 mi
Registration #15	2015-05-20	25.277 mi
Registration #16	2015-05-20	25.277 mi
Registration #17	2015-05-20	25.277 mi
Registration #18	2015-05-20	25.277 mi
Registration #19	2015-05-20	25.277 mi
Registration #20	2015-05-20	25.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1445 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number	D118628
---------------	---------