



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E



Internet history

Entry 1

Date	2021-08-06
Pictures	3
Listing price	View report



source: **cargurus.co.uk**



MOT history

MOT expiry date	2024-08-20
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #15 2023-08-21 13:09

MOT test number 300925522950

Result ✓ Passed

Next expiry date 2024-08-20

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn edge (5.2.3 (e))

MOT #14 2022-08-20 09:20

MOT test number 217584312324

Result ✓ Passed

Advice Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Tyre slightly damaged/cracking or perishing all four cracks (5.2.3 (d) (ii))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13 2021-08-11 14:14

MOT test number 905915083479

Result ✓ Passed

**MOT #12**

2021-08-10 13:55

MOT test number

762266988637

Result

✗ Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #11**

2020-11-10 08:59

MOT test number

862791282845

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #10**

2019-11-05 09:14

MOT test number

548777895994

Result

✓ Passed

Advice Chip in windscreen**MOT #9**

2018-12-04 09:30

MOT test number

753773614964

Result

✓ Passed

Advice Nearside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Shock absorbers has slight external damage to the casing o/s and n/s (5.3.2 (b))**Advice** Advise exhaust front flexi

**MOT #8** 2017-11-15 11:58**MOT test number** 153909361535**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rearmost (2.4.G.2)**MOT #7** 2016-09-26 14:44**MOT test number** 323981772583**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #6** 2016-09-26 10:45**MOT test number** 666387067366**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #5** 2015-09-03 09:59**MOT test number** 308641370275**Result** ✓ Passed**Advice** UNDER TRAYS FITTED**MOT #4** 2014-09-03 17:30**MOT test number** 578646744203**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #3 2014-09-03 10:52

MOT test number 758306644201

Result ✗ Failed

Notice Under-trays fitted obscuring some underside components

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #2 2013-09-18 12:18

MOT test number 119871863240

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

MOT #1 2012-09-19 09:53

MOT test number 555713062217

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 August 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-25
Last registration	2023-08-21
Complete history	See info



Registration #1	2009-09-25	14 mi
Registration #2	2012-09-19	24.909 mi
Registration #3	2013-09-18	32.503 mi
Registration #4	2014-09-03	40.333 mi
Registration #5	2014-09-03	40.333 mi
Registration #6	2015-09-03	46.174 mi
Registration #7	2016-09-26	51.421 mi
Registration #8	2016-09-26	51.423 mi
Registration #9	2017-11-15	56.621 mi
Registration #10	2019-09-25	59.377 mi
Registration #11	2019-09-25	59.377 mi
Registration #12	2019-09-25	59.377 mi
Registration #13	2019-09-25	59.377 mi
Registration #14	2019-09-25	59.377 mi
Registration #15	2019-09-25	59.377 mi
Registration #16	2019-09-25	59.377 mi
Registration #17	2019-09-25	59.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629