



RENAULT

NXIIWRE

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LH29 DCI H/R P/V
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-05
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	34
Total items failed	2

MOT #16	2023-09-01 10:38
MOT test number	741841591749
Result	✓ Passed
Next expiry date	2024-09-10
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2023-08-21 12:45

MOT test number

731941371808

Result**✗ Failed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MAJOR

Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

Advice

Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MAJOR

Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #14

2022-08-11 15:38

MOT test number

268900283888

Result**✓ Passed****MOT #13**

2021-09-11 11:31

MOT test number

133363097876

Result**✓ Passed**

**MOT #12** 2020-11-26 15:58**MOT test number** 496689497293**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))**MOT #11** 2020-11-26 12:59**MOT test number** 579643299064**Result** ✗ Failed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2019-11-27 11:47**MOT test number** 995466244917**Result** ✓ Passed**Advice** Nearside Rear tyre various cuts

**MOT #9** 2019-11-22 13:12**MOT test number** 473722521791**Result** ✗ Failed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to limit/ various cuts (5.2.3 (e))
- Advice** Nearside Rear tyre various cuts
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge close to limit/perishing (5.2.3 (e))

MOT #8 2018-11-16 12:58**MOT test number** 138789982478**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge approx 3.2mm lowest point and edge wear (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge approx 3.2mm lowest point and edge wear (5.2.3 (e))

MOT #7 2018-11-15 11:02**MOT test number** 854518536034**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge approx 3.2mm lowest point and edge wear (5.2.3 (e))
- MAJOR** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge approx 3.2mm lowest point and edge wear (5.2.3 (e))

MOT #6 2017-12-12 16:27**MOT test number** 755752469952**Result** ✓ Passed



MOT #5	2017-03-11 09:49
---------------	------------------

MOT test number	701082070412
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-03-07 15:50
---------------	------------------

MOT test number	372247306862
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-03-05 14:14
---------------	------------------

MOT test number	725104765090
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-02-26 09:17
---------------	------------------

MOT test number	707647154074
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2014-02-26 09:14
---------------	------------------

MOT test number	999717654009
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
-------------	--

Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
-------------	---



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
10 September 2024

Tax status	Valid until 1 September
-------------------	-------------------------

Days left	124
------------------	-----

MOT expiry date	10 September 2024
------------------------	-------------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	NX11WRE
Plate since	2019-09-29
Current registration	NX11WRE
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-07
Last registration	2023-09-01
Complete history	See info



Registration #1	2011-03-07	25 mi
Registration #2	2014-02-26	52.521 mi
Registration #3	2014-02-26	52.521 mi
Registration #4	2015-03-05	69.064 mi
Registration #5	2016-03-07	79.850 mi
Registration #6	2017-03-11	98.761 mi
Registration #7	2017-12-12	108.190 mi
Registration #8	2018-11-15	112.489 mi
Registration #9	2018-11-16	112.517 mi
Registration #10	2019-05-29	112.517 mi
Registration #11	2019-05-29	112.517 mi
Registration #12	2019-05-29	112.517 mi
Registration #13	2019-05-29	112.517 mi
Registration #14	2019-05-29	112.517 mi
Registration #15	2019-05-29	112.517 mi
Registration #16	2019-05-29	112.517 mi
Registration #17	2019-05-29	112.517 mi
Registration #18	2019-05-29	112.517 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	2464 mm
Length	5182 mm
Kerb weight	1745 kg
Max. allowed weight	3010 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C111420