



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT GL
Colour	Grey
Year of manufacture	2009
Top speed	108 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	116 Nm at 4.200 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2021-03-26
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	3

MOT #12	2020-03-24 12:19
MOT test number	252142625915
Result	✓ Passed
Next expiry date	2021-03-26

MOT #11	2020-03-24 12:19
MOT test number	114998804187
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10	2019-03-26 11:11
MOT test number	844787237543
Result	✓ Passed

MOT #9	2019-03-26 11:11
MOT test number	998275517890
Result	✗ Failed
Pass with rectification	Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))

**MOT #8**

2018-03-27 14:01

MOT test number

130264462428

Result

✓ Passed

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #7**

2017-01-04 14:17

MOT test number

649613175338

Result

✓ Passed

Advice Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6**

2017-01-04 10:26

MOT test number

385396754718

Result

✗ Failed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Brake pipe excessively corroded main (3.6.B.2c)**Advice** Offside Front coil spring corroded (2.4.C.1b)

**MOT #5** 2016-01-14 13:34**MOT test number** 684082374637**Result** ✓ Passed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Coil spring corroded front and rear n/s and o/s (2.4.C.1b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2015-01-20 13:17**MOT test number** 397860225020**Result** ✓ Passed**MOT #3** 2014-01-04 11:00**MOT test number** 376334104090**Result** ✓ Passed**MOT #2** 2012-10-01 17:18**MOT test number** 707665372283**Result** ✓ Passed**MOT #1** 2012-08-29 10:41**MOT test number** 326162042282**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
26 January 2021

X

MOT

Expired:
26 March 2021

Tax status	Expired at 26 January 2021
Days left	1188 days too late
MOT expiry date	26 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-09-01
Last registration	2020-03-24
Complete history	See info



Registration #1	2009-09-01	6 mi
Registration #2	2012-08-29	31.249 mi
Registration #3	2012-10-01	31.553 mi
Registration #4	2014-01-04	38.606 mi
Registration #5	2015-01-20	45.090 mi
Registration #6	2016-01-14	47.966 mi
Registration #7	2017-01-04	50.408 mi
Registration #8	2018-01-01	55.000 mi
Registration #9	2018-01-01	55.000 mi
Registration #10	2018-01-01	55.000 mi
Registration #11	2018-01-01	55.000 mi
Registration #12	2018-01-01	55.000 mi
Registration #13	2018-01-01	55.000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3880 mm
Wheel base	2380 mm
Kerb weight	1045 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2169787