



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TDI (80BHP)
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	195 Nm at 2.200 rpm
Engine capacity	1.400 cc
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-06
Pictures	2
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-25
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	47
Total items failed	14

MOT #18	2023-07-05 13:09
MOT test number	183088785998
Result	✓ Passed
Next expiry date	2024-07-25

MOT #17	2023-07-05 13:09
MOT test number	877432432446
Result	✗ Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #16	2022-07-26 14:52
MOT test number	919563568514
Result	✓ Passed
Advice	Engine and under covers fitted obscuring some components
Advice	Offside Rear Nail in tyre
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2022-07-26 14:52**MOT test number** 954433114592**Result** ✗ Failed**Pass with rectification** Headlamp aim too low both side (4.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Engine and under covers fitted obscuring some components**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #14** 2021-04-30 15:11**MOT test number** 426393711956**Result** ✓ Passed**Advice** Engine and under covers fitted obscuring some components**MOT #13** 2020-01-02 14:05**MOT test number** 567334142096**Result** ✓ Passed**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both (5.1.2 (b) (i))**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills and floor (6.1.1 (c) (i))

**MOT #12**

2019-01-10 13:41

MOT test number

127571276387

Result

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracked (5.2.3 (d) (ii))
- Advice** Cambelt due??
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracked & 3mm remaining (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm 185/60 14 (5.2.3 (e))
- Advice** Clutch biting high

MOT #11

2019-01-04 17:01

MOT test number

229157383893

Result

✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm 185/60 14 (5.2.3 (e))
- Advice** Cambelt due??
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracked (5.2.3 (d) (ii))
- Advice** Clutch biting high
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracked & 3mm remaining (5.2.3 (d) (ii))

**MOT #10**

2018-01-27 10:54

MOT test number

864614525353

Result

✓ Passed

Advice

Cambelt due??

Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice

Offside Rear Tyre cracking

Advice

EML on dash

Advice

Oil topped up 1 ltr

MOT #9

2018-01-27 10:54

MOT test number

578257296438

Result

✗ Failed

Advice

Offside Rear Tyre cracking

Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice

EML on dash

Advice

Oil topped up 1 ltr

Pass with rectification

Nearside Stop lamp not working (1.2.1b)

Advice

Cambelt due??

MOT #8

2016-08-22 09:58

MOT test number

671516305286

Result

✓ Passed

**MOT #7** 2016-08-20 08:35**MOT test number** 334342440715**Result** ✗ Failed**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2015-08-08 11:09**MOT test number** 525100225202**Result** ✓ Passed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #5** 2015-08-08 09:09**MOT test number** 316210925250**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**MOT #4** 2014-07-26 09:50**MOT test number** 988907504211**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #3** 2013-08-24 10:50**MOT test number** 306236033419**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Near side front tyre 3mm**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-08-24 10:50**MOT test number** 335676533263**Result** ✗ Failed**Pass with rectification** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Notice** Near side front tyre 3mm**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2012-05-28 12:38**MOT test number** 396099742155**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YY09CKL
Plate since	2019-06-29
Current registration	YY09CKL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-21
Last registration	2023-07-05
Complete history	See info



Registration #1	2009-04-21	18 mi
Registration #2	2012-05-28	58.370 mi
Registration #3	2013-08-24	63.532 mi
Registration #4	2014-07-26	68.621 mi
Registration #5	2015-08-08	75.243 mi
Registration #6	2015-08-08	75.243 mi
Registration #7	2016-08-20	80.981 mi
Registration #8	2016-08-22	80.982 mi
Registration #9	2018-01-27	87.954 mi
Registration #10	2018-01-27	87.954 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BNV136712