



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Black
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-04
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-08-11
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	1

MOT #15	2021-08-12 12:17
MOT test number	262204769167
Result	✓ Passed
Next expiry date	2022-08-11

MOT #14	2021-08-10 16:26
MOT test number	627032307820
Result	✗ Failed
MAJOR	Oil leaking excessively from transmission (8.4.1 (a) (i))
MAJOR	Front Shock absorbers has an excessively worn bush both (5.3.2 (c))

MOT #13	2020-06-24 14:29
MOT test number	565522606087
Result	✓ Passed
Advice	Oil leak, but not excessive top engine (8.4.1 (a) (i))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12	2019-07-01 08:34
MOT test number	939203788935
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11** 2018-06-27 12:55**MOT test number** 177157332958**Result** ✓ Passed**MOT #10** 2018-06-27 12:09**MOT test number** 779943298916**Result** ✗ Failed

**MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**DANGEROUS** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #9** 2017-06-29 10:30**MOT test number** 848447863884**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2017-06-28 07:08**MOT test number** 648107446488**Result** ✗ Failed

**Advice** Oil leak

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-08-19 09:21**MOT test number** 900913742397**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2015-01-21 11:45**MOT test number** 687231225031**Result** ✓ Passed**MOT #5** 2014-02-17 11:06**MOT test number** 659458444072**Result** ✓ Passed**Notice** Both front tyres wearing from the outer edges.**MOT #4** 2013-02-15 10:51**MOT test number** 126716243404**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-02-22 09:39**MOT test number** 659813152031**Result** ✓ Passed**MOT #2** 2011-02-18 10:24**MOT test number** 865419441042**Result** ✓ Passed



MOT #1	2010-02-05 11:19
MOT test number	241896930095
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 August 2022

✕  
MOT

Expired:  
11 August 2022

Tax status	Expired at 31 August 2022
Days left	606 days too late
MOT expiry date	11 August 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-02-28
Last registration	2021-08-12
Complete history	<a href="#">See info</a>



Registration #1	2007-02-28	8 mi
Registration #2	2010-02-05	16.019 mi
Registration #3	2011-02-18	23.649 mi
Registration #4	2012-02-22	31.191 mi
Registration #5	2013-02-15	38.687 mi
Registration #6	2014-02-17	45.338 mi
Registration #7	2015-01-21	49.266 mi
Registration #8	2016-08-19	55.976 mi
Registration #9	2017-06-28	58.679 mi
Registration #10	2018-06-28	61.382 mi
Registration #11	2019-06-28	64.085 mi
Registration #12	2020-06-28	66.788 mi
Registration #13	2021-06-28	69.491 mi
Registration #14	2022-06-28	72.194 mi
Registration #15	2023-06-28	74.897 mi
Registration #16	2024-06-28	77.600 mi
Registration #17	2025-06-28	80.303 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

G4EE7705908