




report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS EGS PICASSO
Colour	Purple
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2

Date	2022-03-01
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-08
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	32
Total items failed	10

MOT #18	2024-02-19 11:06
MOT test number	369977404911
Result	✓ Passed
Next expiry date	2025-02-18
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #17	2023-01-17 11:56
MOT test number	865759120672
Result	✓ Passed

MOT #16	2022-01-25 08:55
MOT test number	886037791715
Result	✓ Passed

**MOT #15**

2021-01-27 09:31

MOT test number

598768158164

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 215 55 16 w (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

MOT #14

2021-01-27 09:31

MOT test number

145030974526

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Drive shaft joint worn, but not excessively (6.1.7 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 215 55 16 w (5.2.3 (e))

**MOT #13**

2020-01-20 15:21

MOT test number

572626653802

Result

✓ Passed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2020-01-20 10:44

MOT test number

789652213322

Result

✗ Failed

Fail

Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Fail

Windscreen washer not working (3.5 (a))

Fail

Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Coolant leak

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11

2019-01-22 11:36

MOT test number

339027025191

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Items removed from driver's view prior to test

Advice

Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2019-01-21 10:44**MOT test number** 984007460516**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9** 2018-01-24 12:54**MOT test number** 166834562009**Result** ✓ Passed**MOT #8** 2017-02-27 16:10**MOT test number** 541705924533**Result** ✓ Passed**MOT #7** 2016-08-18 08:10**MOT test number** 787836204391**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2015-08-13 12:32**MOT test number** 946065325297**Result** ✓ Passed

**MOT #5** 2014-08-21 10:20**MOT test number** 588633734294**Result** ✓ Passed**Notice** All four tyres starting to perish and crack**MOT #4** 2014-08-21 10:20**MOT test number** 948923534265**Result** ✗ Failed**Notice** All four tyres starting to perish and crack**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2013-08-15 10:25**MOT test number** 475527023263**Result** ✓ Passed**Notice** All tyres cracked**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2012-08-20 14:02**MOT test number** 198843632255**Result** ✓ Passed**MOT #1** 2012-08-20 14:02**MOT test number** 599983432217**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Front Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
18 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YD59HFY
Plate since	2019-03-29
Current registration	YD59HFY
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-24
Last registration	2024-02-19
Complete history	See info



Registration #1	2009-09-24	27 mi
Registration #2	2012-08-20	7.865 mi
Registration #3	2013-08-15	13.119 mi
Registration #4	2014-08-21	25.280 mi
Registration #5	2015-08-13	34.442 mi
Registration #6	2016-08-18	44.979 mi
Registration #7	2017-02-27	49.899 mi
Registration #8	2018-01-24	65.639 mi
Registration #9	2019-01-21	72.783 mi
Registration #10	2019-01-22	72.809 mi
Registration #11	2019-01-22	72.809 mi
Registration #12	2019-01-22	72.809 mi
Registration #13	2019-01-22	72.809 mi
Registration #14	2019-01-22	72.809 mi
Registration #15	2019-01-22	72.809 mi
Registration #16	2019-01-22	72.809 mi
Registration #17	2019-01-22	72.809 mi
Registration #18	2019-01-22	72.809 mi
Registration #19	2019-01-22	72.809 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1680 mm
Length	4470 mm
Wheel base	2728 mm
Kerb weight	1499 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBN0169964