



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | MAZDA          |
| Model               | 6 D S          |
| Colour              | Silver         |
| Year of manufacture | 2009           |
| Top speed           | 125 mph        |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 140 BHP             |
| Max. torque             | 330 Nm at 2.000 rpm |
| Engine capacity         | 1.998 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 42.2 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 50.4 mpg            |
| CO2 emission            | 147 g/km            |
| CO2 label               | F                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-07                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-03-07 |
| MOT pass rate      | 75 %       |
| MOT passed         | 12         |
| Failed MOT tests   | 4          |
| Total advice items | 12         |
| Total items failed | 7          |

|                  |                  |
|------------------|------------------|
| MOT #16          | 2023-02-20 17:27 |
| MOT test number  | 219362033126     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-03-07       |

|                 |   |
|-----------------|---|
| MOT #15         | 2023-02-18 14:57  |
| MOT test number | 585122586736  |
| Result          | ✗ Failed  |
| Fail            | Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps and offside rear (4.7.2 (a)) |
| Fail            | Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))   |
| Fail            | Offside Front Brake load sensing valve linkage defective and function impaired (1.1.17 (a))                                   |

|                 |   |
|-----------------|---|
| MOT #14         | 2022-03-02 17:13  |
| MOT test number | 964226051959  |
| Result          | ✓ Passed  |
| Advice          | Vehicle is Heavily Under-sealed.                                    |
| Advice          | Under-chassis, Suspension, Exhaust & Brake components corroded.     |
| Advice          | Covers Fitted On Sills and Arches (Inner & Outer) & Heavy Underseal |
| Advice          | Engine Covers / Under-trays Fitted                                  |

**MOT #13** 2021-03-01 09:48**MOT test number** 630162248200**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-03-02 11:30**MOT test number** 374393850015**Result** ✓ Passed**MOT #11** 2019-03-04 16:49**MOT test number** 736545639110**Result** ✓ Passed**MOT #10** 2019-03-04 14:17**MOT test number** 203675055876**Result** ✗ Failed**Fail** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9** 2018-03-08 12:24**MOT test number** 994886827391**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2017-03-03 15:57**MOT test number** 459390711845**Result** Passed**MOT #7** 2017-03-03 11:22**MOT test number** 371009668994**Result** Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #6** 2016-03-04 12:53**MOT test number** 439491888826**Result** Passed**MOT #5** 2016-03-04 12:53**MOT test number** 338061046407**Result** Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2015-03-05 15:29**MOT test number** 897234665073**Result** Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-03-04 13:04**MOT test number** 625613664021**Result** Passed**MOT #2** 2013-03-05 11:44**MOT test number** 848034663002**Result** Passed



|                 |                  |
|-----------------|------------------|
| MOT #1          | 2012-02-21 11:23 |
| MOT test number | 357652452081     |
| Result          | ✓ Passed         |



Tax & MOT check

X

Untaxed

Tax expired:  
9 October 2023

X

MOT

Expired:  
7 March 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 9 October 2023       |
| Days left        | 203 days too late               |
| MOT expiry date  | 7 March 2024                    |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>RV09ZGW</b> |
| Plate since          | 2019-09-28     |
| Current registration | <b>RV09ZGW</b> |
| Plate since          | 2019-09-28     |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2009-03-04               |
| Last registration          | 2023-02-20               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-03-04 | 8 mi      |
| Registration #2  | 2012-02-21 | 45.096 mi |
| Registration #3  | 2013-03-05 | 55.570 mi |
| Registration #4  | 2014-03-04 | 64.580 mi |
| Registration #5  | 2015-03-05 | 75.399 mi |
| Registration #6  | 2016-03-04 | 83.452 mi |
| Registration #7  | 2016-03-04 | 83.452 mi |
| Registration #8  | 2017-03-03 | 92.075 mi |
| Registration #9  | 2017-03-03 | 92.079 mi |
| Registration #10 | 2018-03-03 | 92.079 mi |
| Registration #11 | 2018-03-03 | 92.079 mi |
| Registration #12 | 2018-03-03 | 92.079 mi |
| Registration #13 | 2018-03-03 | 92.079 mi |
| Registration #14 | 2018-03-03 | 92.079 mi |
| Registration #15 | 2018-03-03 | 92.079 mi |
| Registration #16 | 2018-03-03 | 92.079 mi |
| Registration #17 | 2018-03-03 | 92.079 mi |
| Registration #18 | 2018-03-03 | 92.079 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 77%                             |
| Children       | 81%                             |
| Pedestrian     | 49%                             |
| Safety systems | 71%                             |
| Overall rating | 72%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1795 mm |
| Height              | 1440 mm |
| Length              | 4755 mm |
| Wheel base          | 2725 mm |
| Kerb weight         | 1530 kg |
| Max. allowed weight | 2075 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 64 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | RF 10233898      |