

Ford



General information

FORD
FUSION ZETEC
Blue
2010
107 mph
13.6 seconds
4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I








Internet history

Entry 2	
Date	2021-11-10
Pictures	10
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-09
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	10
Total items failed	5

MOT #18	2023-12-18 14:04
MOT test number	379481380702
Result	✓ Passed
Next expiry date	2024-12-20

MOT #17		2023-12-14 13:26
MOT test	number	734336103086
Result		× Failed
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.1	4 (a) (ii))

MOT #16	2022-12-20 15:55
MOT test number	637718475103
Result	✓ Passed





MOT #15	2021-12-21 12:40
MOT test number	591288038518
Result	✓ Passed
MOT #14	2021-05-25 10:21
MOT test number	414773061043
Result	✓ Passed
Advice Front Brake pad(s) wearing thin n/s	and o/s inner (1.1.13 (a) (ii))
MOT #12	

MOT #13	2021-05-25 10:21
MOT test number	572810979936
Result	× Failed
Pass with rectification	Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))
Advice Front Brake pade	s) wearing thin n/s and o/s inner (1.1.13 (a) (ii))

MOT #12	2020-06-11 11:00
MOT test number	723389457019
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2019-06-17 14:22
MOT test number	208694438978
Result	🗸 Passed
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2018-06-15 13:42
MOT test number	810519987981
Result	✓ Passed





MOT #9	2017 10 04 14.12
	2017-10-04 14:12
MOT test number	808884413530
Result	✓ Passed
MOT #8	2016-10-03 12:22
MOT test number	603479053225
Result	✓ Passed
MOT #7	2015-10-02 10:24
MOT test number	364961892017
Result	✓ Passed
MOT #6	2014-10-02 17:31
MOT test number	289125874271
Result	✓ Passed
MOT #5	2014-10-02 17:31
MOT test number	818265074261
Result	× Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
МОТ #4	2014-04-28 09:16
MOT test number	928288414150
Result	✓ Passed
МОТ #3	2014-04-28 09:16

MOT test number	307408314196	
Result	🗙 Failed	
Pass with rectification	ass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Pass with rectification	ication Nearside Front Windscreen wiper does not clear the windscreen effectively	
(8.2.2)		





MOT #2	2013-04-30 09:50
MOT test number	876800823185
Result	✓ Passed
MOT #1	2013-02-04 09:41
MOT test number	968425433053
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ мот
Tax due: 1 December 2024	Expires: 20 December 2024
Tax status	Valid until 1 December
Days left	217
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Carrent registration Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-29
Last registration	2023-12-18
Complete history	See info



Registration #1	2010-03-29	19 mi
Registration #2	2013-02-04	14.798 mi
Registration #3	2013-04-30	15.756 mi
Registration #4	2014-04-28	20.143 mi
Registration #5	2014-10-02	2.175 mi
Registration #6	2015-10-02	21.928 mi
Registration #7	2016-10-03	28.471 mi
Registration #8	2017-10-04	36.808 mi
Registration #9	2018-06-15	37.351 mi
Registration #10	2019-06-17	47.262 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		10.277 est





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	AP59922