





report date: 2024-03-29

General information

Make	BMW
Model	125 125I M SPORT
Colour	Blue
Year of manufacture	2012
0 - 60 mph	6.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	218 BHP
Engine capacity	1.995 сс
Cylinders	6
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	35.8 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2022-01-17


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-07-17
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	25
Total items failed	7

MOT #12	2023-07-18 10:02
MOT test number	986337330020
Result	✓ Passed
Next expiry date	2024-07-17
Advice Offside Front Headlamp has a product on the lens but not seriously (b))	reducing light output (4.1.4

MOT #11	2022-06-01 11:20
MOT test number	166536410271
Result	✓ Passed

Result		✓ Passed
MOT #10		2021-06-01 11:22
MOT test	number	428958567280
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm outer edge. (5.2	.3 (e))
Advice	Nearside Rear Nail in tyre	
Advice	Oily residue on fuel filter.	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm outer edge. (5	.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm outer edge. (5.2.	3 (e))

CarCheck.co.uk page 3/13



MOT #9 2021-05-28 08:15

MOT test number 542943153475

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm outer edge. (5.2.3 (e))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm outer edge. (5.2.3 (e))

Advice Oily residue on fuel filter.

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm outer edge. (5.2.3 (e))

Fail Offside Side repeater not working (4.4.1 (a) (ii))

MOT #8 2020-06-06 08:50

MOT test number 796181999243

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn very near limit bald inner edge. (5.2.3 (e))

MOT #7 2020-05-30 08:26

MOT test number 297539419128

Result × Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn very near limit bald inner edge. (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm worn to cords. (5.2.3 (e))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/13



Result

LV12LAE report date: 2024-03-29

× Failed

MOT #6 2019-04-06 10:42

MOT test number 227855088520

Result
✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2019-04-06 10:42

MOT test number 308155713801

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2018-04-13 11:58

MOT test number 186305457201

Result Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Under trays fitted not allowing full inspection to underside of vehicle

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2017-03-30 13:30

MOT test number 455130921613

Result J Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Nail in tyre

Advice Vehicle has covers fitted unable to see certain testable items

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2015-03-17 13:42
MOT test number	989836875067
Result	✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITEL	HISLULY

, ,		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		0.00
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-30
Last registration	2023-07-18
Complete history	See info



Registration #1	2012-03-30	14 mi
Registration #2	2015-03-17	57.293 mi
Registration #3	2016-04-14	63.089 mi
Registration #4	2017-03-30	68.926 mi
Registration #5	2018-04-13	75.847 mi
Registration #6	2019-04-06	81.994 mi
Registration #7	2019-04-06	81.994 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.177 mi

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1748 mm
Height	1408 mm
Length	4360 mm
Wheel base	2660 mm
Max. allowed weight	1935 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	5
Engine number	76178234

CarCheck.co.uk page 13/13