



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Blue
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2024-09-14
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	71
Total items failed	9

MOT #162023-09-09 13:23

MOT test number179657502565

Result✓ Passed

Next expiry date2024-09-14

- Advice**Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice**Rear Exhaust mounting defective (6.1.2 (a))
- Advice**Oil leak under covers fitted
- Advice**Rear All suspension components corroded
- Advice**Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Nearside Front Play in steering rack inner joint(s)
- Minor**Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice**Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice**Nearside side repeater lens defective has no effect on emitted light
- Advice**Exhaust hangers corroded
- Advice**Front exhaust flexi deteriorated

**MOT #15**

2022-08-31 12:27

MOT test number

600966157730

Result

✓ Passed

- Minor** Offside Rear Position lamp incorrect colour (4.2.3 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (both) (1.1.14 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Minor** Nearside Rear Position lamp incorrect colour (4.2.3 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14

2021-09-14 08:05

MOT test number

667403625306

Result

✓ Passed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #13**

2020-09-15 14:28

MOT test number

386514080616

Result

✓ Passed

- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Side wall. No cords exposed at time of test. (5.2.3 (d) (ii))
- Advice** Rear Exhaust mounting defective Mount broken (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Under trays fitted obscured view of full inspection check.
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing Side wall. No cord exposed at time of test. (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Edges worn (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2020-09-15 10:29

MOT test number

583855059488

Result**✗ Failed****Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Side wall. No cords exposed at time of test. (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Anti-roll bar linkage fractured Link pin broken (5.3.3 (b) (ii))**Advice** Rear Exhaust mounting defective Mount broken (6.1.2 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing Side wall. No cord exposed at time of test. (5.2.3 (d) (ii))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Under trays fitted obscured view of full inspection check.**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Edges worn (5.2.3 (e))

**MOT #11**

2019-09-09 12:41

MOT test number

813026812135

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened o/s + n/s (1.1.14 (a) (ii))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

MOT #10

2018-09-10 15:52

MOT test number

984135572473

Result

✓ Passed

- Advice** Rear exhaust bracket broken
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Both rear coil springs have slight corrosion to bottom of spring
- Advice** Both front suspension arm pin or bushes slightly worn but not resulting in excessive movement
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Under trays fitted

**MOT #9** 2018-09-10 12:26**MOT test number** 201250294948**Result** ✗ Failed**Advice** Both front suspension arm pin or bushes slightly worn but not resulting in excessive movement**Advice** Under trays fitted**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear exhaust bracket broken**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Both rear coil springs have slight corrosion to bottom of spring**Fail** Nearside Rear Anti-roll bar linkage insecurely attached bolt has snapped no longer connected to anti roll bar (5.3.3 (a) (i))**MOT #8** 2017-03-10 11:25**MOT test number** 177879323885**Result** ✓ Passed**MOT #7** 2017-02-02 16:47**MOT test number** 358463177617**Result** ✓ Passed**MOT #6** 2016-01-16 11:53**MOT test number** 896641104669**Result** ✓ Passed**Advice** Nearside Rear Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #5** 2016-01-16 11:28**MOT test number** 690566223445**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)**MOT #4** 2015-01-24 14:50**MOT test number** 168974025073**Result** ✓ Passed**MOT #3** 2015-01-17 13:37**MOT test number** 768907415043**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Fail** Offside Side repeater not working (1.4.A.2c)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2014-01-13 09:35**MOT test number** 106813414495**Result** ✓ Passed**MOT #1** 2013-01-12 10:54**MOT test number** 459732113063**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-29
Last registration	2023-09-09
Complete history	See info



Registration #1	2010-01-29	16 mi
Registration #2	2013-01-12	28.194 mi
Registration #3	2014-01-13	38.545 mi
Registration #4	2015-01-17	49.939 mi
Registration #5	2015-01-24	50.151 mi
Registration #6	2016-01-16	60.701 mi
Registration #7	2016-01-16	60.701 mi
Registration #8	2017-02-02	70.636 mi
Registration #9	2017-03-10	70.643 mi
Registration #10	2017-03-10	70.643 mi
Registration #11	2017-03-10	70.643 mi
Registration #12	2017-03-10	70.643 mi
Registration #13	2017-03-10	70.643 mi
Registration #14	2017-03-10	70.643 mi
Registration #15	2017-03-10	70.643 mi
Registration #16	2017-03-10	70.643 mi
Registration #17	2017-03-10	70.643 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AS14346