





### General information

Make	HYUNDAI
Model	I40 CRDI STYLE
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	138 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





# MOT history

MOT expiry date	2024-07-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #11	2023-07-11 11:07
MOT test number	177529214356
Result	✓ Passed
Next expiry date	2024-07-10
Advice Nearside Rear suspension bolt balance weight insecure	

МОТ #10	2022-07-05 10:31
MOT test number	192605504336
Result	✓ Passed
Advice Offside Rear suspension bolt balance weight insecure	

МОТ #9	2022-07-04 08:56
MOT test number	455994731377
Result	🗙 Failed
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Offside Rear suspension bolt balance weight insecure	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	



MOT #8	2021-06-21 08:55
MOT test number	318248465454
Result	✓ Passed
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	
Advice Radiator mount missing. Radiator slightly loose.	
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

MOT #7	2020-07-10 15:52
MOT test number	726559280947
Result	✓ Passed
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #6	2020-07-10 10:45
MOT test number	752820515018
Result	🗙 Failed
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #5	2019-03-30 11:54
MOT test number	105205862629
Result	✓ Passed

MOT #4	2018-03-20 12:09
MOT test number	792896933048
Result	✓ Passed

**EN62ZGA** 

report date: 2024-03-28





MOT #3	2017-04-05 08:16
MOT test number	439487974586
Result	Passed
MOT #2	2017-02-07 10:45
MOT test number	506984977117
Result	Passed
MOT #1	2016-02-08 16:23
MOT test number	608819989749
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

<b>Taxed</b> <b>Tax due:</b> 1 September 2024	MOT Expires: 10 July 2024
Tax status	Valid until 1 September
Days left	126
MOT expiry date	10 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*********	
And a second sec	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-02-04
Last registration	2023-07-11
Complete history	See info



Registration #1	2013-02-04	17 mi
Registration #2	2016-02-08	39.545 mi
Registration #3	2017-02-07	57.480 mi
Registration #4	2017-04-05	58.474 mi
Registration #5	2018-03-20	65.435 mi
Registration #6	2019-03-30	73.293 mi
Registration #7		11,777 44
Registration #7 Registration #8		1.77 44
-		01,000 est 01,000 est 01,000 est
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est
Registration #8 Registration #9		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1659 kg
Max. allowed weight	2150 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Num	ber	of	axl	es

### **Engine number**

#### D4FDDU275854