





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE TRENDLINE TDI (100BHP)
Colour	Blue
Year of manufacture	2005
Top speed	119 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-23


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT expiry date	2023-05-12
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	35
Total items failed	14

MOT #23	2022-05-13 14:30
MOT test number	619068277983
Result	✓ Passed
Next expiry date	2023-05-12

MO1 #22		2022-03-11 09.49
MOT test	number	931679778324
Result		X Failed
MAJOR	Offside Rear Direction indicator not working (4.4.1 (a) (ii))	
MAJOR	Nearside Rear Windscreen wiper blade missing (3.4 (b) (ii))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	

MOT #21		2021-05-21 12:41
MOT test i	number	800088116312
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/15



Result

FD05GWY

report date: 2024-03-29

× Failed

MOT #20 2020-06-06 12:21

MOT test number 173153508139

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19 2020-06-06 12:21

MOT test number 728622557486

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #18 2019-05-31 06:56

MOT test number 168286036190

Result \(\sqrt{Passed} \)

MOT #17 2018-06-16 12:03

MOT test number 770493813376

Result

Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MAJOR

Driver's airbag obviously inoperative (7.1.5 (c))

MOT #15

MOT test number

836657364387

Result

Advice N/s wiper blade split

Advice Play in steering rack inner joint(s)

Advice Top and lower engine covers fitted not allowing full inspection

MOT #14 2017-06-12 08:05 191837307504 **MOT** test number Result × Failed **Advice** Play in steering rack inner joint(s) **Advice** N/s wiper blade split Fail Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Top and lower engine covers fitted not allowing full inspection Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

 MOT #13
 2016-05-24 12:21

 MOT test number
 921320693252

 Result
 ✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #12

MOT test number

228448325451

Result

Notice Play in steering rack inner joint(s)

MOT #11

MOT test number

636178125182

Result

Notice Play in steering rack inner joint(s)

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

Fail Front registration plate deteriorated (6.3.1d)

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Play in steering rack inner joint(s)

MOT #9

MOT test number

Result

Notice Play in steering rack inner joint(s)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #8

MOT test number

967994722180

Result

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #7

MOT test number

Result

Notice Play in steering rack

Notice Front brakes have a judder

Notice Offside rear tyre close to limit 2mm

MOT #6 2011-05-04 11:55 **MOT** test number 749444021182 Result × Failed Notice Front brakes have a judder Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Notice Offside rear tyre close to limit 2mm **Notice** Play in steering rack Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #5
 2010-05-06 13:44

 MOT test number
 114666720157

 Result
 ✓ Passed

 MOT #4
 2010-02-04 14:09

 MOT test number
 362275330014

 Result
 ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #	3	2009-04-14 14:44
MOT to	est number	253734209476
Result		✓ Passed
MOT #	2	2008-05-27 14:28
MOT te	est number	782448748109
Result		✓ Passed
MOT #	1	2008-05-23 15:04
MOT to	est number	812664848108
Result		× Failed
Fail	Nearside Front Power steering pipe(s) or hose(s) leaking (2.3.3b)	
Fail	Offside Front brake disc excessively pitted (3.5.1h)	
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Front brake disc excessively pitted (3.5.1h)	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check





Tax status	Expired at 18 January 2023
Days left	468 days too late
MOT expiry date	12 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29


Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Date Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner history

e union motory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-05-31
Last registration	2022-05-13
Complete history	See info



Registration #1	2005-05-31	26 mi
Registration #2	2008-05-23	42.180 mi
Registration #3	2008-05-27	42.180 mi
Registration #4	2009-04-14	48.729 mi
Registration #5	2010-02-04	55.501 mi
Registration #6	2010-05-06	55.505 mi
Registration #7	2011-05-04	81.081 mi
Registration #8	2011-05-04	81.085 mi
Registration #9	2012-05-03	93.460 mi
Registration #10	2013-05-08	103.798 mi
Registration #11	2014-05-08	121.198 mi
Registration #12	2015-05-08	131.731 mi
Registration #13	2015-05-08	131.731 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		71.777 es
Registration #25		11.777 es



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1746 mm
Height	1462 mm
Length	4703 mm
Wheel base	2703 mm
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

CarCheck.co.uk page 15/15

Number of axles	2

Engine number AVB 382931