



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | VOLVO |
| Model | XC60 D4 SE |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.0 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 178 BHP |
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 124 g/km |
| CO2 label | D |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2021-04-01 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 8 |
| Total items failed | 5 |

MOT #6 2020-04-02 12:25

MOT test number 493612330999

Result ✓ Passed

Next expiry date 2021-04-01

Advice Rear Tyre worn close to legal limit/worn on edge both wearing inner edge and close to limit (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2020-04-02 11:12

MOT test number 517392905515

Result ✗ Failed

Fail Front Registration plate does not conform to the specified requirements (0.1 (d))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge both wearing inner edge and close to limit (5.2.3 (e))

Fail Rear Registration plate does not conform to the specified requirements (0.1 (d))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

**MOT #4** 2019-06-08 10:25**MOT test number** 503823784376**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-06-08 10:25**MOT test number** 562290595735**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2018-06-16 12:18**MOT test number** 261594503849**Result** ✓ Passed**MOT #1** 2017-06-22 11:26**MOT test number** 161181814762**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2014-06-06 |
| Last registration | 2020-04-02 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2014-06-06 | 6 mi |
| Registration #2 | 2017-06-22 | 35.233 mi |
| Registration #3 | 2018-06-16 | 45.346 mi |
| Registration #4 | 2019-06-08 | 63.976 mi |
| Registration #5 | 2020-04-02 | 75.277 mi |
| Registration #6 | 2020-04-02 | 75.277 mi |
| Registration #7 | 2020-04-02 | 75.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 94% |
| Children | 79% |
| Pedestrian | 48% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2120 mm |
| Height | 1713 mm |
| Length | 4644 mm |
| Wheel base | 2774 mm |
| Kerb weight | 1781 kg |
| Max. allowed weight | 2330 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1062918 |