



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	PROACE L1 ICON
Colour	Black
Year of manufacture	2020
Top speed	105 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 300 rpm
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	42.2 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-10-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-10-29
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2025-04-11
MOT pass rate	50 %
MOT passed	2
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #4	2024-04-12 15:32
MOT test number	202236245301
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Panel and sill damaged
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Nail in tyre

**MOT #3** 2024-04-12 15:32**MOT test number** 137163265109**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Panel and sill damaged**MOT #2** 2023-02-02 14:35**MOT test number** 665092185101**Result** ✓ Passed**MOT #1** 2023-02-02 12:16**MOT test number** 154350895156**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Nail in tyre



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	FG69TKX
Plate since	2019-03-28
Current registration	FG69TKX
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2020-02-18
Last registration	2024-04-12
Complete history	See info



Registration #1	2020-02-18	20 mi
Registration #2	2020-02-18	25,377 mi
Registration #3	2020-02-18	25,377 mi
Registration #4	2023-02-02	37.994 mi
Registration #5	2020-02-18	25,377 mi
Registration #6	2020-02-18	25,377 mi
Registration #7	2020-02-18	25,377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	91%
Pedestrian	64%
Safety systems	78%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1910 mm
Length	4959 mm
Kerb weight	1240 kg
Max. allowed weight	2640 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	YH00021723