



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI 105
Colour	Grey
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 4

Date	2021-08-30
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

Date	2021-08-06
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-07-09
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1


Date	2021-06-12
------	------------

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-02-16
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	11
Total items failed	14

MOT #18 2023-02-17 18:31**MOT test number** 589227044649**Result** Passed**Next expiry date** 2024-02-16**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2022-02-11 13:25**MOT test number** 506050989077**Result** Passed**MOT #16** 2020-12-12 12:02**MOT test number** 338594714651**Result** Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15**

2019-12-21 09:27

MOT test number

938847007983

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14

2019-12-19 10:26

MOT test number

270171486543

Result

✗ Failed

Fail

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement both sides rear wishbone bushes worn (5.3.4 (a) (i))

Fail

Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail

Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Electronic parking brake warning indicates a malfunction Hand brake light flashing (1.1.6 (e))

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2018-12-15 12:46

MOT test number

763031600161

Result

✓ Passed

MOT #12

2017-12-16 10:59

MOT test number

355327925087

Result

✓ Passed

**MOT #11** 2017-12-16 10:06**MOT test number** 958798115876**Result** ✗ Failed**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #10** 2016-12-20 10:27**MOT test number** 208124706309**Result** ✓ Passed**MOT #9** 2016-12-19 11:21**MOT test number** 152732638984**Result** ✗ Failed**Fail** Offside Front Seat belt stitching badly frayed (5.2.2b)**MOT #8** 2015-12-14 12:30**MOT test number** 362982981992**Result** ✓ Passed**MOT #7** 2015-12-14 09:48**MOT test number** 426546009420**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2014-12-19 11:25**MOT test number** 319603654342**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-12-06 15:42**MOT test number** 149540643329**Result** Passed**MOT #4** 2013-12-06 09:31**MOT test number** 336750343349**Result** Failed**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2012-12-12 11:32**MOT test number** 518827042384**Result** Passed**MOT #2** 2012-12-12 11:32**MOT test number** 106057742354**Result** Failed**Pass with rectification** Offside Front constant velocity joint is insecure (2.5.C.1b)**MOT #1** 2011-12-12 10:03**MOT test number** 486156641344**Result** Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
16 February 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	16 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-12-22
Last registration	2023-02-17
Complete history	See info



Registration #1	2008-12-22	20 mi
Registration #2	2011-12-12	49.553 mi
Registration #3	2012-12-12	56.869 mi
Registration #4	2013-12-06	68.712 mi
Registration #5	2013-12-06	68.712 mi
Registration #6	2014-12-19	77.232 mi
Registration #7	2015-12-14	84.822 mi
Registration #8	2015-12-14	84.822 mi
Registration #9	2016-12-19	90.015 mi
Registration #10	2016-12-20	90.015 mi
Registration #11	2017-12-16	92.877 mi
Registration #12	2018-05-29	95.377 mi
Registration #13	2018-05-29	95.377 mi
Registration #14	2018-05-29	95.377 mi
Registration #15	2018-05-29	95.377 mi
Registration #16	2018-05-29	95.377 mi
Registration #17	2018-05-29	95.377 mi
Registration #18	2018-05-29	95.377 mi
Registration #19	2018-05-29	95.377 mi
Registration #20	2018-05-29	95.377 mi
Registration #21	2018-05-29	95.377 mi
Registration #22	2018-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1251 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE B29276