






report date: 2024-03-29

General information

Make	BMW
Model	X6 XDRIVE40D M SPORT
Colour	Black
Year of manufacture	2011
Top speed	147 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	302 BHP
Max. torque	600 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 3

 Date
 2022-02-01

 Pictures
 0

Listing price <u>View report</u>

source: autotrader.co.uk

Entry 2

 Date
 2021-10-26

 Pictures
 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2021-10-13

 Pictures
 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	25
Total items failed	8

MOT #12	2023-06-27 13:10
MOT test number	102179130161
Result	✓ Passed
Next expiry date	2024-07-12
Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing Si (d) (ii))	idewall slightly damaged (5.2.3

MOT #11	2022-06-13 13:35
MOT test number	420149754392
Result	✓ Passed
Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2022-06-13 11:57
MOT test number	779778958285
Result	× Failed
Fail Offside Rear Outer Tyre has a cut in excess of the requirements deep enough to records Wall (5.2.3 (d) (i))	each the ply or
Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Outer Tyre has a cut in excess of the requirements deep enough to cords Wall (5.2.3 (d) (i))	reach the ply or

CarCheck.co.uk page 3/13



Result

PN61WMF

report date: 2024-03-29

Passed

MOT #9 2021-07-13 15:34

MOT test number 638258359966

Result \rightarrow Passed

Advice Undertrays fitted obscuring some underside components

MOT #8 2020-08-28 10:02

MOT test number 890475092770

Advice Brake pad warning light on but pads ok

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #7 2020-08-28 10:02

MOT test number 429945723827

Result X Failed

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Pass with rectification Offside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Brake pad warning light on but pads ok

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #6 2019-08-19 09:15

MOT test number 761733585706

Result

Passed

Advice Undertrays fitted obscuring some underside components

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #5 2019-08-16 08:22 670048624876 **MOT** test number Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Undertrays fitted obscuring some underside components Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) Fail **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

Fesult

Advice Undertrays fitted obscuring some underside components

Advice Offside Rear Nail in tyre

MOT test number

389435904133

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2015-08-11 16:51
MOT test	number	195843525284
Result		✓ Passed
MOT #1		2014-08-07 10:03
MOT test	number	556239314200
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

,		
For how long did the current and previous owner(s) have this BMW? How many owners defined the current and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	NIN CONTRACTOR	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-01
Last registration	2023-06-27
Complete history	See info



Registration #1	2011-09-01	26 mi
Registration #2	2014-08-07	34.783 mi
Registration #3	2015-08-11	44.293 mi
Registration #4	2017-04-12	59.960 mi
Registration #5	2018-08-30	71.157 mi
Registration #6	2019-08-16	84.080 mi
Registration #7	2019-08-19	84.082 mi
Registration #8	2020-08-28	92.414 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1933 mm
Height	1776 mm
Length	4857 mm
Wheel base	2933 mm
Kerb weight	2110 kg
Max. allowed weight	2790 kg

Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 31387671