





report date: 2024-03-28

General information

| Make | AUDI |
|---------------------|-----------------------|
| Model | A8 S8 QUATTRO FSI V10 |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 604 BHP |
|-------------------------|---------------------|
| Max. torque | 540 Nm at 3.500 rpm |
| Engine capacity | 5.204 cc |
| Cylinders | 10 |
| Fuel type | Petrol |
| Consumption city | 14.2 mpg |
| Consumption extra urban | 28.8 mpg |
| Consumption combined | 20.9 mpg |
| CO2 emission | 319 g/km |
| CO2 label | М |



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-04

Pictures 49

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2024-06-17 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 14 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 2 |

| MOT #16 | | 2023-06-15 15:02 |
|-----------|--|------------------|
| MOT test | number | 244220995245 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-06-17 |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a)) | |
| Advice | Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #15 | 2022-06-09 10:50 |
|---|------------------|
| MOT test number | 984742901057 |
| Result | ✓ Passed |
| Advice Underbody covers fitted parts and structure are obscured | |

| MOT #14 | 2021-06-11 11:27 |
|-----------------|------------------|
| MOT test number | 230650599393 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2020-06-18 08:50 **MOT test number** 483633713244 Result ✓ Passed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Nearside Rear Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e)) Advice **Advice** Yellow brake pad warning light on (pads good) Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

| MOT #12 | 2019-05-20 16:02 |
|--|------------------|
| MOT test number | 333844509896 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2018-07-05 11:52 |
| MOT test number | 201517119951 |
| Result | ✓ Passed |
| Advice Central Rear Registration plate insecure but not likely to fall off (0.1 (a)) | |

| MOT #10 | 2017-07-06 16:55 |
|-----------------------------------|------------------|
| MOT test number | 268809725203 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2016-07-07 07:39 |
| MOT test number | 928841009656 |
| Result | ✓ Passed |
| Advice Nearside Rear nail in tyre | |

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #8 | 2016-07-07 07:39 |
|-------------------------|--|
| MOT test number | 947313347663 |
| Result | × Failed |
| Advice Nearside Rear na | ail in tyre |
| Pass with rectification | Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| MOT #7 | 2015-07-08 10:19 |
| MOT test number | 815979785131 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2014-06-23 15:19 |
| MOT test number | 237814274138 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2013-06-27 09:37 |
| MOT test number | 196908573181 |
| Result | ✓ Passed |

| MOT #4 | 2012-06-27 10:56 |
|-----------------|------------------|
| MOT test number | 339859972160 |
| Result | ✓ Passed |

| MOT #3 | 2011-06-28 17:00 |
|-----------------|------------------|
| MOT test number | 207539271453 |
| Result | ✓ Passed |

| MOT #2 | 2011-06-28 10:24 |
|--------|------------------|

MOT test number 625509571101 Result × Failed

Fail Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 5/13



report date: 2024-03-28

 MOT #1
 2010-06-21 11:17

 MOT test number
 864532470100

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 306 |
| MOT expiry date | 17 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | M |
| Single payment (12 months) | £ 695,00,- |
| Single six month payment | £ 382,25,- |
| Total payable by 12 monthly instalments | £ 729,75,- |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| Owner matery | |
|--|-------------|
| For how long did the current and previous owner(s) have this AUDI? How many owners did check it in the premium report and see all owner registrations. Download the full report is | |
| ******** | |
| | |
| ************ | |
| | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| Number of plates | , |
| Current registration | NK SIK |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2007-06-22 |
| Last registration | 2023-06-15 |
| Complete history | See info |



| Registration #1 | 2007-06-22 | 29 mi |
|------------------|------------|-----------|
| Registration #2 | 2010-06-21 | 17.238 mi |
| Registration #3 | 2011-06-28 | 24.483 mi |
| Registration #4 | 2011-06-28 | 24.483 mi |
| Registration #5 | 2012-06-27 | 39.633 mi |
| Registration #6 | 2013-06-27 | 52.222 mi |
| Registration #7 | 2014-06-23 | 56.309 mi |
| Registration #8 | 2015-07-08 | 62.452 mi |
| Registration #9 | 2016-07-07 | 65.542 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 91.777 es |
| Registration #16 | | 0.00 44 |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |

More info >

CarCheck.co.uk page 12/13



Car features

| The AUDI factory car options list is only available in the premium report. | |
|--|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| \$0567 | |

View the complete AUDI factory list for this vehicle <u>here</u>.

More info >

Safety ratings

S0569

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1897 mm |
|---------------------|---------|
| Height | 1424 mm |
| Length | 5062 mm |
| Wheel base | 2944 mm |
| Max. allowed weight | 2540 kg |

Additional information

| Fuel tank capacity | 90 |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 13/13 |

Engine number

BSM 001621