





report date: 2024-03-29

General information

Make	DACIA
Model	LOGAN LAUREATE SCE
Colour	Red
Year of manufacture	2018
Top speed	98 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	97 Nm at 3.500 rpm
Engine capacity	1.000 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 2

Date 2021-09-02

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-08-29


Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-15
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #5		2023-08-15 13:31
MOT test	number	560787008432
Result		✓ Passed
Next expiry date 2024-08-		2024-08-15
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2023-08-15 13:31
MOT test number		413015765338
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Items removed from driver's view prior to test from interior mirror

MOT test number

Failed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MAJOR

Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice

Items removed from driver's view prior to test from interior mirror

MOT #1	2021-07-30 08:04
MOT test number	479775860409
Result	✓ Passed

CarCheck.co.uk page 4/11



ND180VY report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this DACIA. See if, where and when this DACIA had damage and the car repair costs. We also check if this DACIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra DACIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



ND18OVY

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this DACIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this DACIA? How many owners did this DACIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this DACIA had different number plates. ober of plates faste since

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this DACIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DACIA has been settled.

If not, and you buy this DACIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this DACIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-08-16
Last registration	2023-08-15
Complete history	See info



Registration #1	2018-08-16	19 mi
Registration #2	2021-07-30	55.096 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.177 es

More info >

CarCheck.co.uk page 10/11



ND18OVY

report date: 2024-03-29

Safety ratings

NCAP rating	大大大 大大
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1552 mm
Length	4501 mm
Wheel base	2635 mm
Kerb weight	1071 kg
Max. allowed weight	1555 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R095984

CarCheck.co.uk page 11/11