




report date: 2024-03-29

General information

Make	VOLVO
Model	V70 T5 SE
Colour	Red
Year of manufacture	2003
Top speed	150 mph
0 - 60 mph	7.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	250 BHP
Max. torque	330 Nm at 2.400 rpm
Engine capacity	2.319 cc
Cylinders	5
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	34.4 mpg
Consumption combined	26.2 mpg
CO2 emission	254 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-19
MOT pass rate	83 %
MOT passed	19
Failed MOT tests	4
Total advice items	26
Total items failed	9

MOT #23 2023-07-20 09:33**MOT test number** 137477876019**Result** ✓ Passed**Next expiry date** 2024-08-19**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Play in steering rack inner joint(s)**MOT #22** 2022-08-03 14:31**MOT test number** 601624928190**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #21** 2022-08-03 12:25**MOT test number** 535588660194**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))**Advice** Play in steering rack inner joint(s)



MOT #20	2021-08-20 16:06
MOT test number	910477438124
Result	✓ Passed
MOT #19	2021-02-05 08:56
MOT test number	431790764261
Result	✓ Passed
MOT #18	2020-02-13 15:06
MOT test number	939322592655
Result	✓ Passed
MOT #17	2019-03-19 09:06
MOT test number	438538530047
Result	✓ Passed
MOT #16	2018-03-09 16:54
MOT test number	644709483319
Result	✓ Passed
MOT #15	2017-03-20 16:52
MOT test number	727205772845
Result	✓ Passed
MOT #14	2016-03-21 11:57
MOT test number	355805331023
Result	✓ Passed
MOT #13	2015-03-17 16:31
MOT test number	798426675099
Result	✓ Passed

**MOT #12**

2015-03-06 14:44

MOT test number

507085865013

Result**✗ Failed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear rear brake binding (3.7.B.1)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Headlamp aim not tested (1.8.A.1c)**MOT #11**

2014-03-13 12:12

MOT test number

589912274050

Result**✓ Passed****MOT #10**

2013-03-14 10:07

MOT test number

566233373071

Result**✓ Passed****MOT #9**

2012-03-15 11:04

MOT test number

468155872026

Result**✓ Passed****Notice** Rear exhaust box mounting broken but system still adequately supported**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #8**

2011-03-17 10:46

MOT test number

118856471047

Result

✓ Passed

Notice Slight binb on off side rear brake**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #7**

2010-03-09 15:48

MOT test number

134108660050

Result

✓ Passed

Notice Rear exhaust mounting bracket corroded and very weak**MOT #6**

2010-03-09 12:32

MOT test number

594648060064

Result

✗ Failed

Notice Rear exhaust mounting bracket corroded and very weak**Pass with rectification** Offside Headlamp aim too low (1.8)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #5**

2009-03-10 15:08

MOT test number

491969369059

Result

✓ Passed

Advice Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)

**MOT #4** 2008-03-10 14:41**MOT test number** 732900078044**Result** ✓ Passed**MOT #3** 2007-03-07 15:13**MOT test number** 413096167067**Result** ✓ Passed**Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)**MOT #2** 2007-03-07 13:58**MOT test number** 762836167099**Result** ✗ Failed**Fail** Offside Outer Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Outer Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2006-03-10 13:01**MOT test number** 103659566089**Result** ✓ Passed**Advice** Nearside Outer Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Outer Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RX03XJB
Plate since	2024-03-29
Current registration	RX03XJB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-03-17
Last registration	2023-07-20
Complete history	See info



Registration #1	2003-03-17	22 mi
Registration #2	2006-03-10	25.991 mi
Registration #3	2007-03-07	36.494 mi
Registration #4	2007-03-07	36.494 mi
Registration #5	2008-03-10	45.325 mi
Registration #6	2009-03-10	53.905 mi
Registration #7	2010-03-09	62.361 mi
Registration #8	2010-03-09	62.336 mi
Registration #9	2011-03-17	70.439 mi
Registration #10	2012-03-15	78.623 mi
Registration #11	2013-03-14	87.413 mi
Registration #12	2014-03-13	95.844 mi
Registration #13	2015-03-06	103.553 mi
Registration #14	2016-03-06	111.867 mi
Registration #15	2017-03-06	120.781 mi
Registration #16	2018-03-06	130.295 mi
Registration #17	2019-03-06	140.409 mi
Registration #18	2020-03-06	151.123 mi
Registration #19	2021-03-06	162.437 mi
Registration #20	2022-03-06	174.251 mi
Registration #21	2023-03-06	186.565 mi
Registration #22	2024-03-06	199.379 mi
Registration #23	2025-03-06	212.693 mi
Registration #24	2026-03-06	226.507 mi
Registration #25	2027-03-06	240.821 mi



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	3175757