



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI CDTI 16V
Colour	Black
Year of manufacture	2008
Top speed	135 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-18
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-29
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	25
Total items failed	6

MOT #18	2023-06-21 14:47
MOT test number	965385826244
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #17	2022-06-30 08:52
MOT test number	288786233872
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Brake pipe corroded, covered in grease or other material both front to rears (rear section of pipe) (1.1.11 (c))

MOT #16	2022-06-27 10:27
MOT test number	120767684551
Result	✗ Failed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material both front to rears (rear section of pipe) (1.1.11 (c))

**MOT #15** 2021-06-30 14:34**MOT test number** 437287208775**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2020-09-04 10:00**MOT test number** 873120657933**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2019-08-28 09:17**MOT test number** 623605132110**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2018-08-24 08:36**MOT test number** 660236625491**Result** ✓ Passed

**MOT #11** 2018-08-17 10:27**MOT test number** 646290175257**Result** ✗ Failed

- MAJOR** Offside Front Brake pipe excessively corroded front to rear (1.1.11 (c))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Brake performance not tested burst pipe at rear (1.2.1 (g))
- DANGEROUS** Nearside Brake pipe leaking on a hydraulic braking system front to rear burst (1.1.11 (b) (ii))

MOT #10 2017-06-19 14:25**MOT test number** 972358400808**Result** ✓ Passed**MOT #9** 2017-06-15 08:39**MOT test number** 886709082428**Result** ✗ Failed

- Fail** Brake pipe excessively corroded front to rear brake pipe at rear (3.6.B.2c)
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside Front front brake binding (3.7.B.1)

MOT #8 2016-07-04 08:55**MOT test number** 182268440272**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-06-29 13:54**MOT test number** 605293141254**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Brake pipe excessively corroded front to rear (3.6.B.2c)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2015-06-29 14:48**MOT test number** 808770485182**Result** ✓ Passed**MOT #5** 2015-06-29 11:53**MOT test number** 376770085159**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #4** 2014-06-20 16:07**MOT test number** 996761074164**Result** ✓ Passed**Notice** Nail in nearside front tyre**MOT #3** 2013-06-19 12:03**MOT test number** 888340273180**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2012-06-27 14:24**MOT test number** 378849972113**Result** ✓ Passed



MOT #1	2011-05-07 15:16
MOT test number	676607221122
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	AA08XMC
Plate since	2024-03-28
Current registration	AA08XMC
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-20
Last registration	2023-06-21
Complete history	See info



Registration #1	2008-05-20	28 mi
Registration #2	2011-05-07	23.149 mi
Registration #3	2012-06-27	27.965 mi
Registration #4	2013-06-19	32.484 mi
Registration #5	2014-06-20	39.737 mi
Registration #6	2015-06-29	42.914 mi
Registration #7	2015-06-29	42.914 mi
Registration #8	2016-06-29	45.932 mi
Registration #9	2016-07-04	45.952 mi
Registration #10	2017-06-15	49.277 mi
Registration #11	2018-06-20	52.552 mi
Registration #12	2019-06-20	55.827 mi
Registration #13	2020-06-20	59.102 mi
Registration #14	2021-06-20	62.377 mi
Registration #15	2022-06-20	65.652 mi
Registration #16	2023-06-21	68.927 mi
Registration #17	2024-06-21	72.202 mi
Registration #18	2025-06-21	75.477 mi
Registration #19	2026-06-21	78.752 mi
Registration #20	2027-06-21	82.027 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1456 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	17356328