



report date: 2024-03-28

General information

Make	AUDI
Model	A3 MPI S LINE
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	41.5 mpg
CO2 emission	162 g/km
CO2 label	G





MOT history

MOT expiry date	2025-04-04
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	76
Total items failed	2

MOT #172024-03-25 17:56

MOT test number933689295864

Result✓ Passed

Next expiry date2025-04-04

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Head light lens damaged.

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Underbody covers fitted

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Suspension component corroded but not seriously weakened All (5.3.3 (b) (i))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #16**

2024-03-18 12:24

MOT test number

604217574253

Result**✗ Failed**

MAJOR Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt N/S+O/S (6.1.7 (g) (ii))

MAJOR Nearside Headlamp aim too high (4.1.2 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Head light lens damaged.

MAJOR Emissions unable to be completed exhaust leak not allowing reading on emissions test (8.2.2.2 (e))

MAJOR Exhaust has a major leak of exhaust gases Multiple locations (6.1.2 (a))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MAJOR Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt N/S+O/S (5.3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Underbody covers fitted

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Rear Suspension component corroded but not seriously weakened All (5.3.3 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Front Coil spring fractured or broken N/S+O/S (5.3.1 (b) (i))

**MOT #15**

2023-04-05 11:29

MOT test number

130053680101

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #14

2023-04-05 11:29

MOT test number

420265258578

Result

✗ Failed

- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

**MOT #13**

2022-02-11 12:17

MOT test number

155918038170

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Drive shaft joint constant velocity boot severely deteriorated Both (6.1.7 (g) (i))
- Advice** Exhaust emits black smoke during acceleration (8.2.1.2 (g))

MOT #12

2021-02-13 10:47

MOT test number

395269584658

Result

✓ Passed

- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11

2021-02-12 14:47

MOT test number

154288554453

Result

✗ Failed

- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10** 2020-01-30 09:45**MOT test number** 344107157211**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #9** 2018-10-19 16:01**MOT test number** 581244593915**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing side wall damage (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8** 2017-10-21 10:50**MOT test number** 768650557456**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 2 mm + perishing (4.1.E.1)**MOT #7** 2016-10-28 16:06**MOT test number** 635841834833**Result** ✓ Passed**MOT #6** 2015-12-03 12:53**MOT test number** 221189311961**Result** ✓ Passed

**MOT #5** 2014-12-05 12:55**MOT test number** 769389034391**Result** ✓ Passed**Notice** O/s/r tyre on 3mm on inner shoulder**Notice** Nail in nearside front tyre**MOT #4** 2013-12-10 12:50**MOT test number** 768804443367**Result** ✓ Passed**MOT #3** 2013-08-21 14:22**MOT test number** 385673033422**Result** ✓ Passed**Notice** Front and rear brake discs corroded**Notice** Front wipers slightly smearing**Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**Notice** Slight corrosion to all shock absorber outer casings**Notice** Rear tyres perishing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Slight oil leak



MOT #2	2013-08-21 12:23
MOT test number	327503033486
Result	✗ Failed
Advice	Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
Notice	Front wipers slightly smearing
Notice	Slight corrosion to all shock absorber outer casings
Notice	Rear tyres perishing
Fail	Offside Rear coil spring broken (2.4.C.1a)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Slight oil leak
Notice	Front and rear brake discs corroded

MOT #1	2012-04-20 16:57
MOT test number	185791412190
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-09
Last registration	2024-03-25
Complete history	See info



Registration #1	2009-03-09	28 mi
Registration #2	2012-04-20	21.040 mi
Registration #3	2013-08-21	30.392 mi
Registration #4	2013-08-21	30.392 mi
Registration #5	2013-12-10	33.748 mi
Registration #6	2014-12-05	40.038 mi
Registration #7	2015-12-03	47.180 mi
Registration #8	2016-10-28	50.339 mi
Registration #9	2017-10-21	56.760 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi
Registration #16	2019-05-20	55.377 mi
Registration #17	2019-05-20	55.377 mi
Registration #18	2019-05-20	55.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1185 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	BSE 786266