



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO 610 LX HDI
Colour	White
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-25
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-28
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	18
Total items failed	5

MOT #18	2023-12-28 16:57
MOT test number	626030224700
Result	✓ Passed
Next expiry date	2024-12-28

MOT #17	2022-12-22 13:48
MOT test number	424817588306
Result	✓ Passed
Advice	Drivers seat has slight movement
Advice	Rear springs corroded

MOT #16	2021-12-29 10:54
MOT test number	836247165419
Result	✓ Passed
Advice	Underside and exhaust corroded

**MOT #15**

2021-07-16 09:01

MOT test number

159468822951

Result

✓ Passed

Minor

Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

Advice

Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

Advice

Tyre slightly damaged/cracking or perishing all tyres (5.2.3 (d) (ii))

Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14

2020-07-07 10:27

MOT test number

917794069237

Result

✓ Passed

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2020-07-03 13:08

MOT test number

145037833264

Result

✗ Failed

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Minor

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #12

2019-07-13 08:18

MOT test number

154170000804

Result

✓ Passed

Minor

Offside Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #11** 2018-07-09 13:36**MOT test number** 808790404323**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-07-09 09:11**MOT test number** 435076426715**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #9** 2017-07-15 09:59**MOT test number** 737818994110**Result** ✓ Passed**MOT #8** 2017-07-15 08:18**MOT test number** 244991493524**Result** ✗ Failed**Fail** Tyre has a tear, caused by separation or partial failure of its structure both rear (4.1.D.1b)**MOT #7** 2016-07-16 09:18**MOT test number** 612888493968**Result** ✓ Passed**MOT #6** 2016-07-16 09:18**MOT test number** 671131542185**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #5** 2015-07-18 10:37**MOT test number** 186169995103**Result** ✓ Passed**MOT #4** 2014-07-14 16:01**MOT test number** 249325394449**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-07-12 12:16**MOT test number** 859003394173**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-07-19 11:41**MOT test number** 366810903204**Result** ✓ Passed**MOT #1** 2012-07-20 14:11**MOT test number** 628682602228**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
28 December 2024

Tax status		Valid until 1 December
Days left		216
MOT expiry date		28 December 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-04-30
Last registration	2023-12-28
Complete history	See info



Registration #1	2009-04-30	26 mi
Registration #2	2012-07-20	33.148 mi
Registration #3	2013-07-19	37.434 mi
Registration #4	2014-07-12	41.338 mi
Registration #5	2014-07-14	41.358 mi
Registration #6	2015-07-18	45.516 mi
Registration #7	2016-07-16	49.539 mi
Registration #8	2016-07-16	49.539 mi
Registration #9	2017-07-15	53.691 mi
Registration #10	2017-07-15	53.691 mi
Registration #11	2018-07-15	57.843 mi
Registration #12	2018-07-15	57.843 mi
Registration #13	2019-07-15	61.995 mi
Registration #14	2019-07-15	61.995 mi
Registration #15	2020-07-15	66.147 mi
Registration #16	2020-07-15	66.147 mi
Registration #17	2021-07-15	70.299 mi
Registration #18	2021-07-15	70.299 mi
Registration #19	2022-07-15	74.451 mi
Registration #20	2023-12-28	78.603 mi

More info >



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982525123