



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | PIXO N-TEC |
| Colour | Red |
| Year of manufacture | 2010 |
| Top speed | 96 mph |
| 0 - 60 mph | 14.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 67 BHP |
| Max. torque | 90 Nm at 3.400 rpm |
| Engine capacity | 996 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 103 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-11 |
| MOT pass rate | 81 % |
| MOT passed | 13 |
| Failed MOT tests | 3 |
| Total advice items | 18 |
| Total items failed | 5 |

| | |
|------------------|--|
| MOT #16 | 2024-02-09 15:38 |
| MOT test number | 458485844745 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-11 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|--|
| MOT #15 | 2024-02-09 10:05 |
| MOT test number | 522282220272 |
| Result | ✗ Failed |
| Fail | Horn sound not in accordance with requirements (7.7 (c)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Fail | Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d)) |
| Fail | Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #14 | 2023-02-07 12:03 |
| MOT test number | 837943514006 |
| Result | ✓ Passed |

**MOT #13** 2022-01-31 10:09**MOT test number** 501659451916**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2021-02-12 17:07**MOT test number** 875945852630**Result** ✓ Passed**MOT #11** 2021-02-09 17:25**MOT test number** 892455399101**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2020-06-02 13:48**MOT test number** 519994383469**Result** ✓ Passed**MOT #9** 2019-11-14 11:05**MOT test number** 112417611929**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material At flexi end (1.1.11 (c))

**MOT #8** 2018-12-12 12:59**MOT test number** 646032793415**Result** ✓ Passed**MOT #7** 2018-08-10 10:14**MOT test number** 719323230053**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2017-08-18 11:14**MOT test number** 323754502643**Result** ✓ Passed**MOT #5** 2016-08-10 09:24**MOT test number** 109839633354**Result** ✓ Passed**MOT #4** 2015-08-03 15:39**MOT test number** 631307943244**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-08-19 13:47**MOT test number** 528431734245**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Nail in nearside rear tyre



| | |
|-----------------|---|
| MOT #2 | 2014-08-19 12:35 |
| MOT test number | 505061634266 |
| Result | ✗ Failed |
| Notice | Nail in nearside rear tyre |
| Notice | Vehicle's internal headlight adjuster altered to recheck lights |
| Fail | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) |

| | |
|-----------------|---|
| MOT #1 | 2013-08-22 14:24 |
| MOT test number | 347324333486 |
| Result | ✓ Passed |
| Notice | Vehicle's internal headlight adjuster altered to recheck lights |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
11 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 11 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2010-09-30 |
| Last registration | 2024-02-09 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-09-30 | 15 mi |
| Registration #2 | 2013-08-22 | 26.267 mi |
| Registration #3 | 2014-08-19 | 35.057 mi |
| Registration #4 | 2014-08-19 | 35.057 mi |
| Registration #5 | 2015-08-03 | 44.111 mi |
| Registration #6 | 2016-08-10 | 49.736 mi |
| Registration #7 | 2017-08-18 | 59.259 mi |
| Registration #8 | 2018-08-10 | 68.053 mi |
| Registration #9 | 2018-12-12 | 68.884 mi |
| Registration #10 | 2019-05-29 | 75.377 mi |
| Registration #11 | 2019-05-29 | 75.377 mi |
| Registration #12 | 2019-05-29 | 75.377 mi |
| Registration #13 | 2019-05-29 | 75.377 mi |
| Registration #14 | 2019-05-29 | 75.377 mi |
| Registration #15 | 2019-05-29 | 75.377 mi |
| Registration #16 | 2019-05-29 | 75.377 mi |
| Registration #17 | 2019-05-29 | 75.377 mi |
| Registration #18 | 2019-05-29 | 75.377 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1630 mm |
| Height | 1470 mm |
| Length | 3565 mm |
| Wheel base | 2360 mm |
| Kerb weight | 855 kg |
| Max. allowed weight | 1250 kg |

Additional information

| | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 112085 |