



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T SE
Colour	Blue
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	240 Nm at 5.300 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	6
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT #17	2021-01-18 17:11
MOT test number	509071124780
Result	✓ Passed
Next expiry date	2022-01-17

MOT #16	2019-01-10 10:34
MOT test number	326221037266
Result	✓ Passed
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #15	2019-01-03 12:16
MOT test number	798361951502
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
MAJOR	Electronic stability control warning lamp indicates a fault (7.12 (e))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #14	2017-12-08 10:09
MOT test number	752259663425
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #13	2017-12-08 10:09
MOT test number	724564056535
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Headlamp aim too high (1.8)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2017-01-06 16:09**MOT test number** 297881110430**Result** ✓ Passed**MOT #11** 2017-01-06 15:54**MOT test number** 699506962734**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**MOT #10** 2017-01-05 09:35**MOT test number** 803974941421**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Offside Headlamp aim too low (1.8)**MOT #9** 2015-12-18 10:36**MOT test number** 145947339025**Result** ✓ Passed**MOT #8** 2014-12-16 14:37**MOT test number** 245060454352**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components

**MOT #7** 2014-12-16 11:48**MOT test number** 419550554347**Result** ✗ Failed

- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front Headlamp aim not tested (1.8.A.1c)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Front Headlamp aim not tested (1.8.A.1c)
- Fail** Exhaust system not adequately supported (7.1.1)

MOT #6 2013-12-10 09:07**MOT test number** 778304243303**Result** ✓ Passed**MOT #5** 2012-12-12 12:55**MOT test number** 186097942309**Result** ✓ Passed

- Notice** N/s/f tyre has slight sidewall damage
- Notice** O/s/f and o/s/r tyres wearing on inner edges

MOT #4 2011-12-12 13:49**MOT test number** 536036241332**Result** ✓ Passed

- Notice** Under trays fitted



MOT #3	2011-12-12 13:35
MOT test number	169426541329
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Notice	Under trays fitted

MOT #2	2010-11-29 09:38
MOT test number	644013030391
Result	✓ Passed

MOT #1	2009-12-02 12:50
MOT test number	741596339371
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 OE56FKF
Plate since	2024-03-29
Current registration	 OE56FKF
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-30
Last registration	2021-01-18
Complete history	See info



Registration #1	2006-11-30	20 mi
Registration #2	2009-12-02	30.427 mi
Registration #3	2010-11-29	38.784 mi
Registration #4	2011-12-12	44.622 mi
Registration #5	2011-12-12	44.622 mi
Registration #6	2012-12-12	50.104 mi
Registration #7	2013-12-10	55.562 mi
Registration #8	2014-12-16	62.628 mi
Registration #9	2014-12-16	62.628 mi
Registration #10	2015-12-18	68.346 mi
Registration #11	2016-12-18	74.064 mi
Registration #12	2017-12-18	79.782 mi
Registration #13	2018-12-18	85.500 mi
Registration #14	2019-12-18	91.218 mi
Registration #15	2020-12-18	96.936 mi
Registration #16	2021-01-18	102.654 mi
Registration #17	2021-01-18	102.654 mi
Registration #18	2021-01-18	102.654 mi
Registration #19	2021-01-18	102.654 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1428 mm
Length	4576 mm
Wheel base	2715 mm
Kerb weight	1427 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	3831081
---------------	---------