



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE FAP DCI 130 SCENIC
Colour	Blue
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	9.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	250 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg





Internet history

Entry 1

Date	2021-06-12
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #15</b>	2020-10-03 07:27
<b>MOT test number</b>	231342796940
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-10-02

<b>MOT #14</b>	2019-03-26 17:35
<b>MOT test number</b>	564164239549
<b>Result</b>	✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #13**

2019-03-23 15:52

**MOT test number**

101706161906

**Result****✗ Failed**

- Advice** Offside Front Nail in tyre
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Rear Nail in tyre
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2018-03-31 15:27

**MOT test number**

950662959276

**Result****✓ Passed**

- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Play in steering rack inner joint(s)

**MOT #11** 2018-03-31 15:27**MOT test number** 251835036180**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Play in steering rack inner joint(s)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #10** 2017-03-30 15:08**MOT test number** 212880961911**Result** ✓ Passed**MOT #9** 2016-05-02 13:39**MOT test number** 765770461715**Result** ✓ Passed**Advice** O/s/f brake disc lipping on edge**Advice** O/s/f track rod end slight play**Advice** N/s/f brake disc lipping on edge**Advice** N/s/f track rod end slight play

**MOT #8** 2015-04-15 12:49**MOT test number** 289345205460**Result** ✓ Passed**Notice** Osf tyre worn on both edges**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Osr wheel slight bind**MOT #7** 2015-04-13 16:12**MOT test number** 578413005168**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Osf tyre worn on both edges**Fail** Nearside Rear Road wheel bead rim badly distorted (4.2.A.1a)**Notice** Osr wheel slight bind**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2014-03-14 12:25**MOT test number** 907743674098**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #5** 2013-01-21 10:47**MOT test number** 885071023064**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2012-01-30 12:37**MOT test number** 527730432089**Result** ✓ Passed**MOT #3** 2012-01-30 10:23**MOT test number** 506200632040**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear reflector missing (1.5.1a)**MOT #2** 2011-01-25 12:02**MOT test number** 948525121003**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)**MOT #1** 2011-01-25 12:02**MOT test number** 126755121468**Result** ✗ Failed**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Brake hose has insufficient room to move, resulting in fouling on any part (3.6.B.4a)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	EX08KUG
Plate since	2019-09-28
Current registration	EX08KUG
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-01
Last registration	2020-10-03
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	11 mi
Registration #2	2011-01-25	24.005 mi
Registration #3	2012-01-30	36.170 mi
Registration #4	2012-01-30	36.170 mi
Registration #5	2013-01-21	44.451 mi
Registration #6	2014-03-14	56.451 mi
Registration #7	2015-04-13	63.036 mi
Registration #8	2015-04-15	63.201 mi
Registration #9	2016-05-20	65.277 mi
Registration #10	2017-05-20	65.277 mi
Registration #11	2018-05-20	65.277 mi
Registration #12	2019-05-20	65.277 mi
Registration #13	2020-05-20	65.277 mi
Registration #14	2021-05-20	65.277 mi
Registration #15	2022-05-20	65.277 mi
Registration #16	2023-05-20	65.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

