



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI
Colour	White
Year of manufacture	2012
Top speed	117 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-28
Pictures	24
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-27
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-18
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	57
Total items failed	10

MOT #15	2023-09-19 11:21
MOT test number	662225791503
Result	✓ Passed
Next expiry date	2024-09-18
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Power steering component has slight seepage from a component steering rack (2.1.5 (a))

MOT #14	2023-09-14 15:36
MOT test number	930031670410
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Minor	Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
Advice	Power steering component has slight seepage from a component steering rack (2.1.5 (a))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13**

2022-09-05 08:17

MOT test number

527191088355

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12

2021-09-02 13:09

MOT test number

830375411079

Result

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Radiator leaking
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11

2020-09-14 09:54

MOT test number

579476334419

Result

✓ Passed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #10**

2020-09-11 10:37

MOT test number

389593737820

Result**✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Front Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9

2019-09-03 12:09

MOT test number

885701958513

Result**✓ Passed**

- Advice** Front both tyres worn on edge`s
- Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8

2019-09-03 11:29

MOT test number

925649522716

Result**✗ Failed**

- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front both tyres worn on edge`s
- Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2018-09-18 10:47**MOT test number** 765663593952**Result** ✓ Passed**MOT #6** 2018-04-10 11:10**MOT test number** 348619422212**Result** ✓ Passed

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #5 2017-03-31 15:52**MOT test number** 729803739392**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear tyre is in poor condition and worn on edges
- Advice** Offside Front Tyre worn close to the legal limit Worn inner edges (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear tyre is in poor condition and worn on edges

**MOT #4** 2016-04-12 11:09**MOT test number** 668104425507**Result** ✓ Passed

- Advice** Offside front tyre on 3mm tread
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside rear tyre inner edge wearing
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #3 2016-04-12 09:26**MOT test number** 888239401265**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside front tyre on 3mm tread
- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside rear tyre inner edge wearing
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2 2015-04-15 10:47**MOT test number** 367515805107**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #12015-04-15 10:47

MOT test number298745605141

Result

Failed

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice

Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
18 September 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 GY12FTF
Plate since	2019-06-29
Current registration	 GY12FTF
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-04-18
Last registration	2023-09-19
Complete history	See info



Registration #1	2012-04-18	9 mi
Registration #2	2015-04-15	35.511 mi
Registration #3	2016-04-12	48.138 mi
Registration #4	2016-04-12	48.138 mi
Registration #5	2017-03-31	54.626 mi
Registration #6	2018-04-10	59.985 mi
Registration #7	2018-09-18	61.092 mi
Registration #8	2019-09-03	68.864 mi
Registration #9	2019-09-03	68.864 mi
Registration #10	2020-09-03	75.352 mi
Registration #11	2020-09-03	75.352 mi
Registration #12	2020-09-03	75.352 mi
Registration #13	2020-09-03	75.352 mi
Registration #14	2020-09-03	75.352 mi
Registration #15	2020-09-03	75.352 mi
Registration #16	2020-09-03	75.352 mi
Registration #17	2020-09-03	75.352 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	109257K