



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN R LINE TDI 4MOTION
Colour	Black
Year of manufacture	2009
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-18
Pictures	36
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-14
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #15	2023-08-15 13:47
MOT test number	895894087071
Result	✓ Passed
Next expiry date	2024-08-14

MOT #14	2022-08-12 17:25
MOT test number	663526943507
Result	✓ Passed

MOT #13	2022-08-04 17:04
MOT test number	461441480198
Result	✗ Failed
<b>MAJOR</b> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2021-07-13 10:20
MOT test number	164224049626
Result	✓ Passed

MOT #11	2020-08-04 08:59
MOT test number	437525040802
Result	✓ Passed

**MOT #10** 2019-07-10 08:48**MOT test number** 130333397299**Result** ✓ Passed**MOT #9** 2018-07-31 14:34**MOT test number** 795915177755**Result** ✓ Passed**MOT #8** 2018-04-16 10:54**MOT test number** 848290273096**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front tyres wearing inside**Advice** Items removed from driver's view prior to test**MOT #7** 2017-04-25 13:35**MOT test number** 579151562874**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2017-04-15 11:07**MOT test number** 597746137184**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Side repeater not working in the mirror (1.4.A.2c)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2016-04-25 09:04**MOT test number** 549148593840**Result** ✓ Passed**MOT #4** 2015-12-04 10:31**MOT test number** 633954139607**Result** ✓ Passed**MOT #3** 2014-12-05 15:51**MOT test number** 618969834358**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-11-22 16:57**MOT test number** 425046923410**Result** ✓ Passed



MOT #1	2012-12-14 12:54
MOT test number	566239142390
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
14 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	14 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YF59CXO
Plate since	2019-03-28
Current registration	YF59CXO
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-15
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2009-12-15	9 mi
Registration #2	2012-12-14	6.943 mi
Registration #3	2013-11-22	10.029 mi
Registration #4	2014-12-05	14.386 mi
Registration #5	2015-12-04	18.519 mi
Registration #6	2016-04-25	19.971 mi
Registration #7	2017-04-15	27.771 mi
Registration #8	2017-04-25	27.909 mi
Registration #9	2018-04-16	36.058 mi
Registration #10	2019-05-20	35.377 mi
Registration #11	2019-05-20	35.377 mi
Registration #12	2019-05-20	35.377 mi
Registration #13	2019-05-20	35.377 mi
Registration #14	2019-05-20	35.377 mi
Registration #15	2019-05-20	35.377 mi
Registration #16	2019-05-20	35.377 mi
Registration #17	2019-05-20	35.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CBA 645974