



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Grey
Year of manufacture	2006
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-27
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-05
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	41
Total items failed	10

MOT #22 2024-03-18 12:58

MOT test number 620260367136

Result ✓ Passed

Next expiry date 2025-04-05

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #21 2023-03-28 14:04

MOT test number 425043853691

Result ✓ Passed

MOT #20 2023-03-28 14:01

MOT test number 844954882343

Result ✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #19**

2023-03-28 09:33

MOT test number

397794853621

Result**✗ Failed**

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front ***strong advise*** tyre heavily worn on inner edge

Fail Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Suspension arm ball joint excessively worn rear most arm (5.3.4 (a) (i))

Advice Offside Front tyre has a slice on outer sidewall but no cords visible

Fail Nearside Front Suspension arm ball joint excessively worn rear most arm (5.3.4 (a) (i))

MOT #18

2022-04-06 10:12

MOT test number

730719334926

Result**✓ Passed**

Advice Slight fluctuation from front brakes

Advice Slight play in both front wheel bearings

MOT #17

2022-04-04 10:06

MOT test number

269200012651

Result**✗ Failed**

Advice Slight fluctuation from front brakes

Fail Parking brake lever ratchet not holding correctly (1.1.6 (a))

Advice Slight play in both front wheel bearings

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #16

2021-03-22 09:33

MOT test number

780919374189

Result**✓ Passed**



MOT #15	2020-03-26 09:41
MOT test number	743289735558
Result	✓ Passed

MOT #14	2019-04-27 09:14
MOT test number	462574402824
Result	✓ Passed
Advice	Nearside front tyre close to legal limit
Advice	Rear coil springs corroded
Advice	Slight play in both front anti roll bar d bushes

MOT #13	2018-04-28 10:41
MOT test number	553931360546
Result	✓ Passed
Advice	FRONT AND REAR BRAKE PADS GETTING LOW
Advice	ENGINE LIGHT ON DASH
Advice	N/S O/S FRONT LOWER ARMS BUSHES PERRISHING
Advice	N/S FRONT DROP LINK SLIGHT PLAY
Advice	UNDERTRAYS FITTED

**MOT #12** 2018-04-28 08:08**MOT test number** 927391001686**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a pin/bush DROPLINK (2.4.G.2)**Advice** UNDERTRAYS FITTED**Advice** FRONT AND REAR BRAKE PADS GETTING LOW**Advice** ENGINE LIGHT ON DASH**Advice** N/S O/S FRONT LOWER ARMS BUSHES PERRISHING**Advice** N/S FRONT DROP LINK SLIGHT PLAY**MOT #11** 2017-01-31 09:28**MOT test number** 923388019085**Result** ✓ Passed**Advice** N/s/f tyre worn low and on dges**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2016-02-04 10:15**MOT test number** 437509536345**Result** ✓ Passed**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Under-trays fitted**Advice** Engine covers fitted**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

**MOT #9** 2015-02-02 10:16**MOT test number** 366253635003**Result** ✓ Passed**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Both front tyres slightly worn on edges**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2013-11-22 09:28**MOT test number** 938046423377**Result** ✓ Passed**MOT #7** 2012-09-14 13:55**MOT test number** 328548152240**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2012-05-09 16:37**MOT test number** 208690732153**Result** ✓ Passed**MOT #5** 2012-05-09 11:13**MOT test number** 555440532111**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2011-05-25 17:02**MOT test number** 869785441183**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-05-25 11:36**MOT test number** 256935041128**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-06-02 11:05**MOT test number** 904283550134**Result** ✓ Passed**MOT #1** 2009-06-05 10:02**MOT test number** 291216259171**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 April 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KY56YLH
Plate since	2019-06-29
Current registration	 KY56YLH
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-06
Last registration	2024-03-18
Complete history	See info



Registration #1	2006-09-06	17 mi
Registration #2	2009-06-05	23.460 mi
Registration #3	2010-06-02	30.847 mi
Registration #4	2011-05-25	36.982 mi
Registration #5	2011-05-25	36.983 mi
Registration #6	2012-05-09	44.896 mi
Registration #7	2012-05-09	44.896 mi
Registration #8	2012-09-14	45.611 mi
Registration #9	2013-11-22	51.091 mi
Registration #10	2015-02-02	58.678 mi
Registration #11	2016-02-04	65.582 mi
Registration #12	2017-01-31	70.218 mi
Registration #13	2018-01-01	75.000 mi
Registration #14	2018-01-01	75.000 mi
Registration #15	2018-01-01	75.000 mi
Registration #16	2018-01-01	75.000 mi
Registration #17	2018-01-01	75.000 mi
Registration #18	2018-01-01	75.000 mi
Registration #19	2018-01-01	75.000 mi
Registration #20	2018-01-01	75.000 mi
Registration #21	2018-01-01	75.000 mi
Registration #22	2018-01-01	75.000 mi
Registration #23	2018-01-01	75.000 mi
Registration #24	2018-01-01	75.000 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030258778