





report date: 2024-03-28

General information

| Make | BMW |
|---------------------|-----------------------------|
| Model | 640 640D M SPORT GRAN COUPE |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.4 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 308 BHP |
|-------------------------|---------------------|
| Max. torque | 630 Nm at 1.500 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 152 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date 2022-03-13

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

| Date 2021-09-03 |
|-----------------|
|-----------------|

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-09-02 | |
|---------------|--------------------|--|
| Pictures | 0 | |
| Listing price | <u>View report</u> | |

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

| B 4 | \sim $-$ | | |
|-------|-------------|------|-------|
| 10.71 | $^{\prime}$ | hic | torv. |
| 101 | C I | 1115 | IUI V |
| | • | | tory |

| MOT expiry date | 2024-10-13 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 0 |

| MOT #7 | 2023-10-07 08:13 |
|---|------------------|
| MOT test number | 378855276425 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-13 |
| Advice Engine under tray fitted | |
| Advice Child Seat fitted not allowing full inspection of adult belt | |

| MOT #6 | | 2022-10-14 15:10 |
|----------------|--|------------------|
| MOT test numbe | r | 153743395352 |
| Result | | ✓ Passed |
| | | |
| MOT #5 | | 2022-10-14 10:59 |
| MOT test numbe | r | 936607968848 |
| Result | | X Failed |
| DANGEROUS | Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |

| MOT #4 | 2022-08-12 15:31 |
|-----------------|------------------|
| MOT test number | 394787646543 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-08-12 11:58

MOT test number 295366538489

MOT #2 2021-08-11 15:53

MOT test number 561104527007

Result X Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2019-08-23 14:56

MOT test number 597231322572

Result ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 156 |
| MOT expiry date | 13 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report | |
|---|-------------|
| *************************************** | |
| | |
| *************************************** | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK ZIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2016-10-14 |
| Last registration | 2023-10-07 |
| Complete history | See info |



| Registration #1 | 2016-10-14 | 26 mi |
|------------------|------------|-----------|
| Registration #2 | 2019-08-23 | 13.716 mi |
| Registration #3 | 2021-08-11 | 22.658 mi |
| Registration #4 | 2021-08-12 | 22.658 mi |
| Registration #5 | | 0.777 es |
| Registration #6 | | 71.777 66 |
| Registration #7 | | 0.777 es |
| Registration #8 | | 71.777 66 |
| Registration #9 | | 9.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.117 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 1894 mm |
|---------------------|---------|
| Height | 1392 mm |
| Length | 5007 mm |
| Wheel base | 2968 mm |
| Kerb weight | 1810 kg |
| Max. allowed weight | 2410 kg |

Additional information

| Fuel tank capacity | 70 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 59519335 |

CarCheck.co.uk page 11/11