



report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SE-L NAV
Colour	Silver
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-09-04
Pictures	9
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-09-04
Pictures	22
Listing price	View report



source: [heycar.co.uk](#)



MOT history

MOT expiry date	2024-06-28
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	17
Total items failed	3

MOT #8	2023-06-05 13:55
MOT test number	225228707799
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge badly worn on both edges (5.2.3 (e))

MOT #7	2023-06-05 10:22
MOT test number	560686154377
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge badly worn on both edges (5.2.3 (e))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #6	2022-06-08 15:42
MOT test number	365223097393
Result	✓ Passed
Advice	Undertrays fitted
Advice	Heat shield loose

**MOT #5** 2022-06-07 14:54**MOT test number** 537930405330**Result** ✗ Failed

- Advice** Undertrays fitted
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Heat shield loose
- Fail** Offside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #4 2021-06-29 12:18**MOT test number** 201115647364**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front brake discs slightly corroded inner faces

MOT #3 2019-07-20 10:19**MOT test number** 149667687772**Result** ✓ Passed

- Advice** Front brake discs slightly corroded inner faces
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracked on the tread (5.2.3 (d) (ii))
- Advice** Rear brake discs corroded inner faces



MOT #2	2019-07-20 08:13
MOT test number	446160455294
Result	✗ Failed
Advice	Front brake discs slightly corroded inner faces
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Cut on the tread (5.2.3 (d) (i))
Advice	Rear brake discs corroded inner faces
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Cracked on the tread (5.2.3 (d) (ii))

MOT #1	2018-08-04 10:58
MOT test number	688124458996
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 June 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-01
Last registration	2023-06-05
Complete history	See info



Registration #1	2015-09-01	22 mi
Registration #2	2018-08-04	28.000 mi
Registration #3	2019-07-20	36.334 mi
Registration #4	2019-07-20	36.334 mi
Registration #5	2021-06-29	57.312 mi
Registration #6	2023-06-05	57.312 mi
Registration #7	2023-06-05	57.312 mi
Registration #8	2023-06-05	57.312 mi
Registration #9	2023-06-05	57.312 mi
Registration #10	2023-06-05	57.312 mi
Registration #11	2023-06-05	57.312 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1475 mm
Length	4800 mm
Wheel base	2750 mm
Kerb weight	1420 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30465172