



RENAULT

LVI2DLK

report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2012
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	58.8 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-07
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	44
Total items failed	10

MOT #18	2023-10-06 14:11
MOT test number	275695261454
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2023-10-06 11:00
MOT test number	157738308668
Result	✗ Failed
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #16**

2022-10-26 12:03

MOT test number

855810603376

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15**

2022-10-25 13:52

MOT test number

277791319378

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #14**

2021-10-08 13:00

MOT test number

287274094096

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Tyre worn close to legal limit/worn on edge front (5.2.3 (e))**Advice** Offside mirror cover missing

**MOT #13**

2021-10-08 10:40

MOT test number

279608835422

Result**✗ Failed**

- MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside mirror cover missing
- Advice** Tyre worn close to legal limit/worn on edge front (5.2.3 (e))
- MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #12

2020-09-22 13:16

MOT test number

771952668951

Result**✓ Passed****MOT #11**

2020-09-21 10:24

MOT test number

719565533877

Result**✗ Failed**

- DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #10** 2019-09-27 11:55**MOT test number** 724507546121**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-09-27 11:55**MOT test number** 141720197835**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-09-24 15:09**MOT test number** 692791956857**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #7** 2018-09-24 10:43**MOT test number** 810080726888**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- MAJOR** Offside Rear Coil spring with an unsafe modification incorrect spring fitted to rear (5.3.1 (d) (i))
- Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Front Play in steering rack inner joint(s)

MOT #6 2017-09-19 09:00**MOT test number** 589329212638**Result** ✓ Passed**MOT #5** 2017-04-07 07:21**MOT test number** 502256808987**Result** ✓ Passed**MOT #4** 2017-04-03 13:13**MOT test number** 776794138800**Result** ✗ Failed

- Fail** Rear fog lamp not working (1.3.2b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #3	2016-03-04 09:14
MOT test number	195430096304
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2	2015-03-16 09:47
MOT test number	585165075039
Result	✓ Passed

MOT #1	2015-03-16 09:47
MOT test number	185345375467
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
25 October 2024

Tax status		Valid until 1 May
Days left		1
MOT expiry date		25 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	LV12DLK
Plate since	2019-03-29
Current registration	LV12DLK
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-30
Last registration	2023-10-06
Complete history	See info



Registration #1	2012-03-30	12 mi
Registration #2	2015-03-16	95.253 mi
Registration #3	2016-03-04	121.444 mi
Registration #4	2017-04-03	147.700 mi
Registration #5	2017-04-07	147.700 mi
Registration #6	2017-09-19	151.659 mi
Registration #7	2018-09-24	154.242 mi
Registration #8	2018-09-24	154.246 mi
Registration #9	2019-09-27	157.082 mi
Registration #10	2019-09-27	157.082 mi
Registration #11	2019-09-27	157.082 mi
Registration #12	2019-09-27	157.082 mi
Registration #13	2019-09-27	157.082 mi
Registration #14	2019-09-27	157.082 mi
Registration #15	2019-09-27	157.082 mi
Registration #16	2019-09-27	157.082 mi
Registration #17	2019-09-27	157.082 mi
Registration #18	2019-09-27	157.082 mi
Registration #19	2019-09-27	157.082 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D037239