






General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E







Internet history	
Entry 1	
Date	2022-02-11
Pictures	2
Listing price	View report

JUST ARRIVED AWAITING PREPARATION

6



source: cargurus.co.uk



MOT history

MOT expiry date	2024-02-15
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #11	2023-02-15 10:53
MOT test number	819551874541
Result	Passed
Next expiry date	2024-02-15
AdviceO/s/f indicator lense damagedAdviceOil leak	

MOT #10	2022-02-16 11:23
MOT test number	359096625885
Result	✓ Passed

MOT #9	2021-03-16 11:06
MOT test number	827702956231
Result	✓ Passed





MOT #8	2020-03-19 12:47
MOT test	number 572244733317
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn inner and outer shoulder (5.2.3 (e))
Advice	Rear exhaust silencer corroded
Advice	Front Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (e))	Nearside Front Tyre worn close to legal limit/worn on edge worn inner and outer shoulder (5.2.3
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7		2020-03-19 09:46
MOT test	number	366745395927
Result		🗙 Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Of	ffside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn inner and outer	shoulder (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
Fail W	indscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Rear exhaust silencer corroded	
Advice	Front Coil spring corroded (5.3.1 (b) (i))	
Advice (e))	Nearside Front Tyre worn close to legal limit/worn on edge worn inner and out	er shoulder (5.2.3





MOT #6	2019-03-13 13:25
MOT test number	353577120818
Result	✓ Passed
Advice Nearside Front Nail in tyre	
MOT #5	2019-03-11 13:37
MOT test number	526746511971
Result	🗙 Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Nearside Front Nail in tyre	

MOT #4		2018-03-13 15:32
MOT test	number	461921273973
Result		✓ Passed
Advice	Offside Front tyre wearing inner and outer edges	
Advice	Nearside Front tyre wearing inner and outer edges	

MOT #3		2018-03-10 09:51
MOT test	number	597274416481
Result		× Failed
Advice	Offside Front tyre wearing inner and outer edges	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Nearside Front tyre wearing inner and outer edges	
Fail Nearside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)		



CU13KTC	
report date: 2024-03-29)

MOT #2	2017-02-27 16:44
MOT test number	278497011692
Result	✓ Passed
MOT #1	2016-03-10 14:33
MOT test number	499356955045
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

√ Taxed	Х МОТ
Tax due: 1 August 2024	Expired: 15 February 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-12
Last registration	2023-02-15
Complete history	<u>See info</u>



Registration #1	2013-03-12	18 mi
Registration #2	2016-03-10	21.583 mi
Registration #3	2017-02-27	29.174 mi
Registration #4	2018-03-10	38.901 mi
Registration #5	2018-03-13	38.903 mi
Registration #6	2019-03-11	49.943 mi
Registration #7	2019-03-13	49.943 mi
Registration #8		11.222 est
Registration #9		11.222 mi
Registration #10		11.222 est
Registration #11		11.222 mi
Registration #12		11.222 est
Registration #13		11.317 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	0272619