





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH DSTYLE PLUS S/S
Colour	Blue
Year of manufacture	2015
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-04-15

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-21
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #10	2024-04-22 10:37
MOT test number	451139462124
Result	✓ Passed
Next expiry date	2025-04-21

MOT #9	2023-04-18 10:39
MOT test number	594326418811
Result	✓ Passed

MOT #8	2022-04-14 02:21
MOT test number	557488044955
Result	✓ Passed

MOT test number	535237101658
MOT #7	2021-10-13 13:34

Result

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #6 2020-10-10 10:45 **MOT** test number 124627179223 ✓ Passed Result **Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) **Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i)) Offside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) Advice Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))

MOT #5 2020-10-10 09:54 262427548415 **MOT test number** Result ★ Failed Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) **Advice Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e)) Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e)) Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

 MOT #4
 2019-10-14 10:04

 MOT test number
 883753724809

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



MOT #3 2019-03-30 11:26

MOT test number 718651325758

Result
✓ Passed

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #2 2018-04-10 12:11

MOT test number 444459077082

MOT #1 2018-04-10 12:11

MOT test number 474235695009

Result X Failed

Pass with rectification Nearside Headlamp aim aimed so that it dazzles other road users incorrectly

fitted bulb (1.8.A.1a)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	21 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full it	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK AIS
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-31
Last registration	2024-04-22
Complete history	See info



2015-03-31	21 mi
2018-04-10	26.035 mi
2018-04-10	26.035 mi
2019-03-30	29.423 mi
2019-10-14	30.562 mi
2020-10-10	39.798 mi
	11.777 es
	2018-04-10 2018-04-10 2019-03-30 2019-10-14

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	XV120055772

CarCheck.co.uk page 12/12